

# Shenzhen TCL Smart Home Technology Co.,Ltd.

Device	TCL D2 Series Smart Door Lock
Company name	Shenzhen TCL Smart Home Technology Co., Ltd.
Grantee code	2BG9T
FCC ID	2BG9T-TCLSMARTD2A
FRN	0035610914
Contact name	Davion Xie
Address	7/F,TCL G1 Building. TCL International E City, No.1001 Zhongshan Yuan Road, Nanshan District,Shenzhen
Telephone number	13045889807
E-mail	jiang2.xie@tcl.com
Chipset/module information	MCU (CCMA2025) / wifi&BLE (BK7236)/NFC(WS1850S)
Operating System (if applicable)	NA
Storage Capacity (hard drive or other permanent memory storage, if applicable)	64Kb

**Item 1.** The device is able to install software/program installation?

☒ Yes, go to Item 2.

☐ No. In this case, the rest of the items do not apply. The device cannot support installation of Kaspersky cybersecurity or anti-virus software.

**Item 2.** Technical Requirements for Kaspersky Cybersecurity Software:

#	General Requirements (For all Devices)	Yes / No or N/A	Comments
1	Internet connection for activation and updates (For all Operating Systems)	YES	WLAN

#	General Requirements (For Windows Devices)	Yes / No or N/A	Comments
1	Storage: 1500 MB free space on the hard drive	NO	
2	Operating System:  Microsoft Windows 8, 8.1, 10 & 11 Home / Pro / Enterprise Microsoft  Windows 7 Starter / Home Basic & Premium / Professional / Ultimate SP1 or higher	NO	No Operating System:
3	Processor: 1 GHz or higher (x86 or x64)	NO	120MHz
4	Memory (RAM)1 GB (32-bit) or 2 GB (64-bit)	NO	64Kb
5	Screen Resolution: Minimum resolution of 1024 x 768	NO	Without screen

#	General Requirements (For macOS devices)	Yes / No or N/A	Comments
1	Operating System macOS® 13 – 14	N/A	
2	Memory (RAM)4 GB	N/A	
3	Storage: 3455 MB free space on the hard drive	N/A	

#	General Requirements (For Android Devices)	Yes / No or N/A	Comments
1	Storage: 150 MB free space	N/A	
2	Operating System: Android™ 10 – 14	N/A	
3	Screen Resolution: Minimum resolution of 320 x 480	N/A	

#	General Requirements (for iOS devices)	Yes / No or N/A	Comments
1	Storage: 150 MB free space	N/A	
2	Operating System: iOS® 17	N/A	

#	General Requirements (For Linux system)	Yes / No or N/A	Comments
---	-----------------------------------------	-----------------	----------

1	Hard drive: 1 GB of free space	N/A	
2	CPU: Intel Pentium 1 GHz or higher	N/A	
3	RAM: 1 GB	N/A	
4	Minimum software requirements:  AlmaLinux OS 8 or later;  AlterOS 7.5 or later;  Astra Linux Common Edition 2.12 or later;  CentOS 6.7 or later;  Debian GNU/Linux 10.0 or later;  EulerOS 2.0 or later;  Oracle Linux 7.3 or later ;  Red Hat Enterprise Linux 6.7 or later ;  Rocky Linux 8.5 or later ;  SUSE Linux Enterprise Server 12.5 or later;  Ubuntu 12.04 or later ;  Uncom OS Home / Business / Education / Enterprise 2.2 or later;  ALT Linux Workstaton / Workstation K / Server / Education 8 or later;  ROSA Linux Workstation / Server 12 or later ;  RED OS 7.3 and later ;	N/A	

**After reviewed the technical requirements, is the device capable of supporting the installation of Kaspersky software?**

☐ Yes, go to Item 3.

☒ No. In this case, the rest of the items do not apply. The device cannot support installation of Kaspersky software

**Item 3. Connectivity Capabilities:**



#	Physical Interface	Purpose	Justification <sup>1</sup>
1	TYPY-C	charging	Limited to power supply

#	Wireless Interface	Purpose	Justification <sup>1</sup>
1	wifi	Connect with internet	Customer can operation the device
2	bluetooth	Support to connect with wifi	No file transfer capability
3	NFC	NFC card can open the lock	Passive mode only

After the review of this items, the device:

☒ Cannot support installation of any cybersecurity or anti-virus software on the covered list.

☐ Potentially can operate with any cybersecurity or anti-virus software on the covered list – additional third-party proof is provided to demonstrate compliance with requirements as of 2.911(d)5(i),(ii) – “Proof of Compliance with Covered List Software Requirements” of this document applies

Signature: 

Name: Davion Xie

Date: 20250519

<sup>1</sup> The justification field is used to justify why the software cannot be received through that interface. Check the annex for more indications.