



15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:44:14

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:44:51

15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:45:30

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:49:55

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:50:31

20MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
 Date: 22,JUL,2024 22:51:07


FCC Part 27

B4 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:20:40

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:22:16

5MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:23:21

10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:25:02

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:26:46

10MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:28:10

15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:29:45

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:31:22

15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:32:54

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:37:50

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 22,JUL,2024 23:41:49


20MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 23,JUL,2024 08:41:12

B7 , Normal


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0




10MHz_Middle_QPSK_1@0



10MHz_High_QPSK_1@0




15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:39:12

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:39:52

15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:40:32

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:43:24

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:44:07


20MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:44:49

B12 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Middle_QPSK_1@0




1.4MHz_High_QPSK_1@0




3MHz_Low_QPSK_1@0




3MHz_Middle_QPSK_1@0



3MHz_High_QPSK_1@0




5MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:54:46

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:55:17

5MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:55:48

10MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:58:25

10MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:58:58


10MHz_High_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 08:59:32


B13 , Normal

5MHz_Low_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:13:26

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:13:39

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:13:52

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:14:05

5MHz_High_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 19:12:08

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 19:12:20

5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 19:12:32

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 19:14:23

10MHz_Middle_QPSK_1@0(30MHz~8.87GHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:16:22

10MHz_Middle_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:16:38

10MHz_Middle_QPSK_1@0(793MHz~806MHz)



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:16:55


10MHz_Middle_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 31.JUL.2024 14:17:11

B17 , Normal


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0



10MHz_Middle_QPSK_1@0




10MHz_High_QPSK_1@0




B38 , Normal


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0




10MHz_Middle_QPSK_1@0



10MHz_High_QPSK_1@0




15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:53:31

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:54:12

15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:54:54

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 09:57:18

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 10:24:49


20MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 10:25:39

B41 , Normal


5MHz_Low_QPSK_1@0




5MHz_Middle_QPSK_1@0




5MHz_High_QPSK_1@0




10MHz_Low_QPSK_1@0




10MHz_Middle_QPSK_1@0



10MHz_High_QPSK_1@0




15MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:27:21

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:28:03

15MHz_High_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:28:44

20MHz_Low_QPSK_1@0




ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:30:55

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:31:36

20MHz_High_QPSK_1@0



ProjectNo.:2402V58055E-RF Tester:Karl Liang
Date: 26.JUL.2024 11:32:18