

In Poor Taste LLC

9436 w lake mead Blvd suite 5 pmb 1098 ,Las Vegas nv 89134

Attestation Statements

To: Federal Communications Commission

Date: May. 26, 25

7435 Oakland Mills Road,

Columbia, MD 21046, USA

Subject: Attestation of Compliance with FCC Covered List Software Requirements

FCC ID: [2BK7J-VENTYCLIP]

Product Name: [Venty fan]

This letter serves as an attestation that the equipment identified above ☐ **is** / ☒ **is not** (select one) "covered" software as defined under the Federal Communications Commission (FCC) Covered List requirements, as outlined in **FCC 22-84** and **KDB 986446**.

Specifically, the undersigned certifies that the equipment for which authorization is sought:

1. **Does not contain** cybersecurity or anti-virus software produced or provided by **Kaspersky Lab, Inc.** or any of its successors, assignees, parents, subsidiaries, affiliates, or any entity that has rebranded or relabeled software produced by the aforementioned entities.
2. **Does not have the capability** to store, run, or deliver any software identified on the FCC Covered List, including but not limited to cybersecurity and anti-virus software.

To support this attestation, the appendix evaluation documentation has been prepared and is included in the certification filing.

This attestation is based on a thorough evaluation of the device's design, functionality, and software environment. The undersigned affirms that the information provided is accurate and complete to the best of their knowledge.

Sincerely yours,

Matthew Scott Slack

Applicant Signature

Name	Matthew Scott Slack
Position	CEO
Company Name	In Poor Taste LLC
Address	9436 w lake mead Blvd suite 5 pmb 1098 ,Las Vegas nv 89134
Tel	+1 (725) 249-8944
Fax	/
Email	matthewslack83@gmail.com

In Poor Taste LLC

9436 w lake mead Blvd suite 5 pmb 1098 ,Las Vegas nv 89134

Evaluation regarding to the Covered List Software:		
Compliance Methodology	Evaluation Process	
Device is Inherent compliance	☒	The Chipset(s) used is limited to run the Cybersecurity or anti-virus software.
	☒	The Memory used is limited to run the Cybersecurity or anti-virus software.
	☒	There is storage capacity limitation for store or install the Cybersecurity or anti-virus software.
	☒	Operating system used is limited to run, install or deliver the Cybersecurity or anti-virus software.
Device is not Inherent compliance	☐	Evaluation Based on Software Bill of Materials (SBoM)
	☐	Evaluation Based on Scan for Software on the device
	☐	Evaluation Based on Filesystem scan
	☐	Evaluation Based on Running software check