



802.11ax160_6825MHz_RU_Full_Chain 1 156MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:11:32

802.11ax160_6665MHz_RU_Full_Chain 1 156.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:08:43

802.11ax160_6825MHz_RU_Full_Chain 2 156MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:45:01

802.11ax160_6665MHz_RU_Full_Chain 2 156MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:40:12

802.11ax160_6825MHz_RU_Full_Chain 3 156.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:26:09

802.11ax160_6665MHz_RU_Full_Chain 3 156.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:23:43

802.11ax20_6535MHz_RU_Full_Chain 0 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 17:45:16

802.11ax20_6695MHz_RU_Full_Chain 0 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 17:47:12

802.11ax20_6855MHz_RU_Full_Chain 0 19.100MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 17:49:29

802.11ax20_6535MHz_RU_Full_Chain 1 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:34:17

802.11ax20_6695MHz_RU_Full_Chain 1 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:36:25

802.11ax20_6855MHz_RU_Full_Chain 1 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:38:45

802.11ax20_6535MHz_RU_Full_Chain 2 18.950MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:52:50

802.11ax20_6695MHz_RU_Full_Chain 2 18.950MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:55:33

802.11ax20_6855MHz_RU_Full_Chain 2 19MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:58:19

802.11ax20_6535MHz_RU_Full_Chain 3 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 08:56:52

802.11ax20_6695MHz_RU_Full_Chain 3 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 08:58:27

802.11ax20_6855MHz_RU_Full_Chain 3 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:00:22

802.11ax40_6565MHz_RU_Full_Chain 0 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 17:58:28

802.11ax40_6685MHz_RU_Full_Chain 0 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:00:10

802.11ax40_6845MHz_RU_Full_Chain 0 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:01:50

802.11ax40_6565MHz_RU_Full_Chain 1 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:46:52

802.11ax40_6685MHz_RU_Full_Chain 1 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:48:28

802.11ax40_6845MHz_RU_Full_Chain 1 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:50:16

802.11ax40_6565MHz_RU_Full_Chain 2 37.800MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:06:31

802.11ax40_6685MHz_RU_Full_Chain 2 37.800MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:08:13

802.11ax40_6845MHz_RU_Full_Chain 2 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:10:55

802.11ax40_6565MHz_RU_Full_Chain 3 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:06:01

802.11ax40_6685MHz_RU_Full_Chain 3 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:07:17

802.11ax40_6845MHz_RU_Full_Chain 3 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 17.DEC.2024 09:08:56

802.11ax80_6865MHz_RU_Full_Chain 0 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:14:39

802.11ax80_6625MHz_RU_Full_Chain 0 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:09:45

802.11ax80_6705MHz_RU_Full_Chain 0 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:11:12

802.11ax80_6785MHz_RU_Full_Chain 0 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:12:53

802.11ax80_6865MHz_RU_Full_Chain 1 77.600MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:03:32

802.11ax80_6625MHz_RU_Full_Chain 1 77.600MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:57:15

802.11ax80_6705MHz_RU_Full_Chain 1 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 18:58:51

802.11ax80_6785MHz_RU_Full_Chain 1 77.200MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 19:01:36

802.11ax80_6865MHz_RU_Full_Chain 2 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:24:57

802.11ax80_6625MHz_RU_Full_Chain 2 77.200MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:18:15

802.11ax80_6705MHz_RU_Full_Chain 2 77.200MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:19:53

802.11ax80_6785MHz_RU_Full_Chain 2 77.200MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 20:21:40


802.11ax80_6865MHz_RU_Full_Chain 3 77.600MHz




802.11ax80_6625MHz_RU_Full_Chain 3 77.400MHz



802.11ax80_6705MHz_RU_Full_Chain 3 77.200MHz




802.11ax80_6785MHz_RU_Full_Chain 3 77.200MHz




U-NII 8


802.11ax160_6985MHz_RU_Full_Chain 0 156MHz




802.11ax160_6985MHz_RU_Full_Chain 1 155.600MHz




802.11ax160_6985MHz_RU_Full_Chain 2 156MHz



802.11ax160_6985MHz_RU_Full_Chain 3 155.600MHz




802.11ax20_6875MHz_RU_Full_Chain 0 19.100MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 10:58:42

802.11ax20_6895MHz_RU_Full_Chain 0 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:02:22

802.11ax20_6995MHz_RU_Full_Chain 0 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:08:43

802.11ax20_7115MHz_RU_Full_Chain 0 18.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:12:07

802.11ax20_6875MHz_RU_Full_Chain 1 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:14:27

802.11ax20_6895MHz_RU_Full_Chain 1 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:16:57

802.11ax20_6995MHz_RU_Full_Chain 1 19.100MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:21:21

802.11ax20_7115MHz_RU_Full_Chain 1 18.950MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:29:02

802.11ax20_6875MHz_RU_Full_Chain 2 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:02:56

802.11ax20_6895MHz_RU_Full_Chain 2 19MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:05:30

802.11ax20_6995MHz_RU_Full_Chain 2 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:10:13

802.11ax20_7115MHz_RU_Full_Chain 2 18.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:13:28

802.11ax20_6875MHz_RU_Full_Chain 3 19.150MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:49:08

802.11ax20_6895MHz_RU_Full_Chain 3 19.100MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:53:33

802.11ax20_6995MHz_RU_Full_Chain 3 19.050MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:58:05

802.11ax20_7115MHz_RU_Full_Chain 3 18.950MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:01:18

802.11ax40_6885MHz_RU_Full_Chain 0 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:17:11

802.11ax40_6925MHz_RU_Full_Chain 0 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:20:08

802.11ax40_6965MHz_RU_Full_Chain 0 37.800MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:23:47

802.11ax40_7085MHz_RU_Full_Chain 0 37.700MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:28:55

802.11ax40_6885MHz_RU_Full_Chain 1 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:32:33

802.11ax40_6925MHz_RU_Full_Chain 1 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:34:38

802.11ax40_6965MHz_RU_Full_Chain 1 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:38:18

802.11ax40_7085MHz_RU_Full_Chain 1 37.700MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:40:57

802.11ax40_6885MHz_RU_Full_Chain 2 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:17:00

802.11ax40_6925MHz_RU_Full_Chain 2 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:18:46

802.11ax40_6965MHz_RU_Full_Chain 2 37.800MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:22:14

802.11ax40_7085MHz_RU_Full_Chain 2 37.800MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:24:51

802.11ax40_6885MHz_RU_Full_Chain 3 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:04:04

802.11ax40_6925MHz_RU_Full_Chain 3 38MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:06:04

802.11ax40_6965MHz_RU_Full_Chain 3 37.900MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:09:32

802.11ax40_7085MHz_RU_Full_Chain 3 37.700MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:12:18

802.11ax80_6945MHz_RU_Full_Chain 0 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:33:44

802.11ax80_7025MHz_RU_Full_Chain 0 77MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 11:37:46

802.11ax80_6945MHz_RU_Full_Chain 1 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:48:59

802.11ax80_7025MHz_RU_Full_Chain 1 77MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 13:52:48

802.11ax80_6945MHz_RU_Full_Chain 2 77.400MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:32:59

802.11ax80_7025MHz_RU_Full_Chain 2 77MHz




ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 14:37:07

802.11ax80_6945MHz_RU_Full_Chain 3 77.400MHz



ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:16:59

802.11ax80_7025MHz_RU_Full_Chain 3 77MHz



ProjectNo.:2401X96326E-RF Tester:Cheeb Huang
Date: 16.DEC.2024 15:25:44