















Freq. Stability 10C 120V ax20 5785MHz Ant1 0 Minutes







Date: 4.JUN.2025 14:56:29

Freq. Stability 30C 120V ax20 5785MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:56:40






Freq. Stability 20C 138V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:59:44

Freq. Stability -20C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 14:59:49


Freq. Stability -10C 120V ax20 5825MHz Ant1 0 Minutes



Freq. Stability 0C 120V ax20 5825MHz Ant1 0 Minutes




Freq. Stability 10C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:05

Freq. Stability 30C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:15

Freq. Stability 40C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:21

Freq. Stability 50C 120V ax20 5825MHz Ant1 0 Minutes




Date: 4.JUN.2025 15:00:26

Freq. Stability 20C 102V ax40 5190MHz Ant1 0 Minutes







Date: 4.JUN.2025 16:20:53



Freq. Stability 20C 120V ax40 5190MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:21:43









Freq. Stability 40C 120V ax40 5190MHz Ant1 0 Minutes




Freq. Stability 50C 120V ax40 5190MHz Ant1 0 Minutes




Freq. Stability 20C 102V ax40 5230MHz Ant1 0 Minutes



Freq. Stability 20C 120V ax40 5230MHz Ant1 0 Minutes




Freq. Stability 20C 138V ax40 5230MHz Ant1 0 Minutes





Date: 4.JUN.2025 16:24:50


Freq. Stability -20C 120V ax40 5230MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:24:57




Freq. Stability 10C 120V ax40 5230MHz Ant1 0 Minutes







Date: 4.JUN.2025 16:25:18

Freq. Stability 30C 120V ax40 5230MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:25:33






Freq. Stability 20C 138V ax40 5270MHz Ant1 0 Minutes






Date: 4.JUN.2025 16:28:50

Freq. Stability -20C 120V ax40 5270MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:28:58











Date: 4.JUN.2025 16:29:19




Date: 4.JUN.2025 16:29:33












Freq. Stability -10C 120V ax40 5310MHz Ant1 0 Minutes




Freq. Stability 0C 120V ax40 5310MHz Ant1 0 Minutes








Freq. Stability 20C 102V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:36:58

Freq. Stability 20C 120V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:37:48

Freq. Stability 20C 138V ax40 5510MHz Ant1 0 Minutes





Date: 4.JUN.2025 16:37:12


Freq. Stability -20C 120V ax40 5510MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:37:20




Freq. Stability 10C 120V ax40 5510MHz Ant1 0 Minutes




Date: 4.JUN.2025 16:37:41

Freq. Stability 30C 120V ax40 5510MHz Ant1 0 Minutes



Date: 4.JUN.2025 16:37:55

Freq. Stability 40C 120V ax40 5510MHz Ant1 0 Minutes



Freq. Stability 50C 120V ax40 5510MHz Ant1 0 Minutes

