

**Due Diligence Letter**  
For Certification Service in the USA

**Federal Communications Commission**  
Equipment Authorization Division, Application Processing Branch  
7435 Oakland Mills Road  
**Columbia, MD 21048**

To whom it may concern

FCC ID	Model name
2BN37-TS34	TS34, TS35, TS36, TS37, TS38, TS39, TS40, TS41, TM5, TM9, TM10, TU05, TU06, TU08, TU09, TU10, TS600, TS610, TS620, TS630

Pursuant to KDB 986446 D01 Covered Equipment Guidance the evaluation of the product above shows compliance for the following reasons:

Compliance		Evaluation process	Results
Inherent compliance	<input checked="" type="checkbox"/>	The chipset(s) used is not capable of running the cybersecurity and/or anti-virus software	Conform
	<input type="checkbox"/>	The memory used does not allow the running the cybersecurity and/or anti-virus software	
	<input type="checkbox"/>	The storage capacity does not allow the running the cybersecurity and/or anti-virus software	
	<input type="checkbox"/>	The operating system used is not capable of running the cybersecurity and/or anti-virus software	
No inherent compliance	<input type="checkbox"/>	Based on software bill of material	
	<input type="checkbox"/>	Based on scan for running software on the device	
	<input type="checkbox"/>	Based on filesystem scan for cybersecurity and/or anti-virus software	

The equipment for which authorization is sought complies with the rules and fulfils the requirements as detailed in the above mentioned KDB.

**Evaluation performed by**

Company Name: Shenzhen Bangce Testing  
Technology Co., Ltd.  
Contact Name: Rory Huang  
Address: 101, building 10, Yunli Intelligent  
Park, Shutianpu community,  
Matian Street, Guangming  
District, Shenzhen, Guangdong,  
China  
Phone: N/A  
Email: N/A

*Rory Huang*