





Band2\_20MHz\_QPSK\_18700\_1RB#0




Band2\_20MHz\_QPSK\_18700\_1RB#99



Band2\_20MHz\_QPSK\_18700\_100RB#0




Band2\_20MHz\_QPSK\_19100\_1RB#0



Band2\_20MHz\_QPSK\_19100\_1RB#99




Band2\_20MHz\_QPSK\_19100\_100RB#0



Band2\_20MHz\_16QAM\_18700\_1RB#0



Band2\_20MHz\_16QAM\_18700\_1RB#99




Band2\_20MHz\_16QAM\_19100\_1RB#0



Band2\_20MHz\_16QAM\_19100\_1RB#99


# Conducted Spurious Emission

## Test Graphs




21:53:38 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#0\_0.009~0.15\_0.009~0.1  
5




21:53:42 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#0\_0.15~30\_0.15~30




21:53:47 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#0\_30~1000\_30~1000




21:53:59 08.01.2024


Band2\_1.4MHz\_QPSK\_18607\_1RB#0\_1000~3000\_1000~300  
0




Band2\_1.4MHz\_QPSK\_18607\_1RB#0\_3000~20000\_3000~20000




Band2\_1.4MHz\_16QAM\_18607\_1RB#0\_0.009~0.15\_0.009~0.15



Band2\_1.4MHz\_16QAM\_18607\_1RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_16QAM\_18607\_1RB#0\_30~1000\_30~1000



21:54:39 08.01.2024

Band2\_1.4MHz\_16QAM\_18607\_1RB#0\_1000~3000\_1000~30


00



21:54:50 08.01.2024

Band2\_1.4MHz\_16QAM\_18607\_1RB#0\_3000~20000\_3000~2


0000



21:54:57 08.01.2024


Band2\_1.4MHz\_QPSK\_18607\_1RB#5\_0.009~0.15\_0.009~0.1

5




21:55:02 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#5\_0.15~30\_0.15~30



21:55:06 08.01.2024


Band2\_1.4MHz\_QPSK\_18607\_1RB#5\_30~1000\_30~1000



21:55:18 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#5\_1000~3000\_1000~300


0



21:55:30 08.01.2024

Band2\_1.4MHz\_QPSK\_18607\_1RB#5\_3000~20000\_3000~20000


000




21:55:37 08.01.2024

Band2\_1.4MHz\_16QAM\_18607\_1RB#5\_0.009~0.15\_0.009~0.15


15




Band2\_1.4MHz\_16QAM\_18607\_1RB#5\_0.15~30\_0.15~30




Band2\_1.4MHz\_16QAM\_18607\_1RB#5\_30~1000\_30~1000



Band2\_1.4MHz\_16QAM\_18607\_1RB#5\_1000~3000\_1000~30  
00




Band2\_1.4MHz\_16QAM\_18607\_1RB#5\_3000~20000\_3000~2  
0000




Band2\_1.4MHz\_QPSK\_18607\_6RB#0\_0.009~0.15\_0.009~0.1


5



Band2\_1.4MHz\_QPSK\_18607\_6RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_QPSK\_18607\_6RB#0\_30~1000\_30~1000




Band2\_1.4MHz\_QPSK\_18607\_6RB#0\_1000~3000\_1000~300


0




Band2\_1.4MHz\_QPSK\_18607\_6RB#0\_3000~20000\_3000~20000




Band2\_1.4MHz\_16QAM\_18607\_6RB#0\_0.009~0.15\_0.009~0.15



Band2\_1.4MHz\_16QAM\_18607\_6RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_16QAM\_18607\_6RB#0\_30~1000\_30~1000



21:57:17 08.01.2024

Band2\_1.4MHz\_16QAM\_18607\_6RB#0\_1000~3000\_1000~30


00



21:57:29 08.01.2024

Band2\_1.4MHz\_16QAM\_18607\_6RB#0\_3000~20000\_3000~2


0000



21:57:40 08.01.2024


Band2\_1.4MHz\_QPSK\_18900\_1RB#0\_0.009~0.15\_0.009~0.1

5




21:57:45 08.01.2024


Band2\_1.4MHz\_QPSK\_18900\_1RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_QPSK\_18900\_1RB#0\_30~1000\_30~1000




Band2\_1.4MHz\_QPSK\_18900\_1RB#0\_1000~3000\_1000~300  
0




Band2\_1.4MHz\_QPSK\_18900\_1RB#0\_3000~20000\_3000~20  
000




Band2\_1.4MHz\_16QAM\_18900\_1RB#0\_0.009~0.15\_0.009~0.  
15




Band2\_1.4MHz\_16QAM\_18900\_1RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_16QAM\_18900\_1RB#0\_30~1000\_30~1000



Band2\_1.4MHz\_16QAM\_18900\_1RB#0\_1000~3000\_1000~30  
00




Band2\_1.4MHz\_16QAM\_18900\_1RB#0\_3000~20000\_3000~2  
0000




Band2\_1.4MHz\_QPSK\_18900\_1RB#5\_0.009~0.15\_0.009~0.1


5



Band2\_1.4MHz\_QPSK\_18900\_1RB#5\_0.15~30\_0.15~30




Band2\_1.4MHz\_QPSK\_18900\_1RB#5\_30~1000\_30~1000




Band2\_1.4MHz\_QPSK\_18900\_1RB#5\_1000~3000\_1000~300

0




21:59:33 08.01.2024

Band2\_1.4MHz\_QPSK\_18900\_1RB#5\_3000~20000\_3000~20000




21:59:39 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_1RB#5\_0.009~0.15\_0.009~0.15




21:59:44 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_1RB#5\_0.15~30\_0.15~30



21:59:48 08.01.2024


Band2\_1.4MHz\_16QAM\_18900\_1RB#5\_30~1000\_30~1000



22:00:00 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_1RB#5\_1000~3000\_1000~30


00



22:00:12 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_1RB#5\_3000~20000\_3000~2


0000



22:00:19 08.01.2024


Band2\_1.4MHz\_QPSK\_18900\_6RB#0\_0.009~0.15\_0.009~0.1

5




22:00:23 08.01.2024

Band2\_1.4MHz\_QPSK\_18900\_6RB#0\_0.15~30\_0.15~30



22:00:28 08.01.2024


Band2\_1.4MHz\_QPSK\_18900\_6RB#0\_30~1000\_30~1000



22:00:40 08.01.2024

Band2\_1.4MHz\_QPSK\_18900\_6RB#0\_1000~3000\_1000~300


0



22:00:52 08.01.2024

Band2\_1.4MHz\_QPSK\_18900\_6RB#0\_3000~20000\_3000~20


000



22:00:58 08.01.2024


Band2\_1.4MHz\_16QAM\_18900\_6RB#0\_0.009~0.15\_0.009~0.

15




22:01:03 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_6RB#0\_0.15~30\_0.15~30



22:01:07 08.01.2024


Band2\_1.4MHz\_16QAM\_18900\_6RB#0\_30~1000\_30~1000



22:01:19 08.01.2024

Band2\_1.4MHz\_16QAM\_18900\_6RB#0\_1000~3000\_1000~30


00



22:01:31 08.01.2024


Band2\_1.4MHz\_16QAM\_18900\_6RB#0\_3000~20000\_3000~2

0000




Band2\_1.4MHz\_QPSK\_19193\_1RB#0\_0.009~0.15\_0.009~0.1


5



Band2\_1.4MHz\_QPSK\_19193\_1RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_QPSK\_19193\_1RB#0\_30~1000\_30~1000




Band2\_1.4MHz\_QPSK\_19193\_1RB#0\_1000~3000\_1000~300

0




22:02:16 08.01.2024

Band2\_1.4MHz\_QPSK\_19193\_1RB#0\_3000~20000\_3000~20000




22:02:23 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#0\_0.009~0.15\_0.009~0.15




22:02:27 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#0\_0.15~30\_0.15~30



22:02:32 08.01.2024


Band2\_1.4MHz\_16QAM\_19193\_1RB#0\_30~1000\_30~1000



22:02:44 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#0\_1000~3000\_1000~30


00



22:02:56 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#0\_3000~20000\_3000~2


0000



22:03:02 08.01.2024


Band2\_1.4MHz\_QPSK\_19193\_1RB#5\_0.009~0.15\_0.009~0.1

5




22:03:07 08.01.2024

Band2\_1.4MHz\_QPSK\_19193\_1RB#5\_0.15~30\_0.15~30



22:03:12 08.01.2024


Band2\_1.4MHz\_QPSK\_19193\_1RB#5\_30~1000\_30~1000



22:03:23 08.01.2024

Band2\_1.4MHz\_QPSK\_19193\_1RB#5\_1000~3000\_1000~300


0



22:03:35 08.01.2024

Band2\_1.4MHz\_QPSK\_19193\_1RB#5\_3000~20000\_3000~20000


000



22:03:42 08.01.2024


Band2\_1.4MHz\_16QAM\_19193\_1RB#5\_0.009~0.15\_0.009~0.15

15




22:03:46 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#5\_0.15~30\_0.15~30




22:03:51 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#5\_30~1000\_30~1000




22:04:03 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#5\_1000~3000\_1000~30  
00




22:04:15 08.01.2024

Band2\_1.4MHz\_16QAM\_19193\_1RB#5\_3000~20000\_3000~2  
0000




Band2\_1.4MHz\_QPSK\_19193\_6RB#0\_0.009~0.15\_0.009~0.1


5



Band2\_1.4MHz\_QPSK\_19193\_6RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_QPSK\_19193\_6RB#0\_30~1000\_30~1000




Band2\_1.4MHz\_QPSK\_19193\_6RB#0\_1000~3000\_1000~300


0




Band2\_1.4MHz\_QPSK\_19193\_6RB#0\_3000~20000\_3000~20000




Band2\_1.4MHz\_16QAM\_19193\_6RB#0\_0.009~0.15\_0.009~0.15



Band2\_1.4MHz\_16QAM\_19193\_6RB#0\_0.15~30\_0.15~30




Band2\_1.4MHz\_16QAM\_19193\_6RB#0\_30~1000\_30~1000




Band2\_1.4MHz\_16QAM\_19193\_6RB#0\_1000~3000\_1000~30

00




Band2\_1.4MHz\_16QAM\_19193\_6RB#0\_3000~20000\_3000~2


0000




Band2\_3MHz\_QPSK\_18615\_1RB#0\_0.009~0.15\_0.009~0.15




Band2\_3MHz\_QPSK\_18615\_1RB#0\_0.15~30\_0.15~30




Band2\_3MHz\_QPSK\_18615\_1RB#0\_30~1000\_30~1000




Band2\_3MHz\_QPSK\_18615\_1RB#0\_1000~3000\_1000~3000



Band2\_3MHz\_QPSK\_18615\_1RB#0\_3000~20000\_3000~2000  
00




Band2\_3MHz\_16QAM\_18615\_1RB#0\_0.009~0.15\_0.009~0.1  
5




22:06:56 08.01.2024

Band2\_3MHz\_16QAM\_18615\_1RB#0\_0.15~30\_0.15~30




22:07:01 08.01.2024

Band2\_3MHz\_16QAM\_18615\_1RB#0\_30~1000\_30~1000




22:07:13 08.01.2024

Band2\_3MHz\_16QAM\_18615\_1RB#0\_1000~3000\_1000~300  
0




22:07:25 08.01.2024

Band2\_3MHz\_16QAM\_18615\_1RB#0\_3000~20000\_3000~20  
000




Band2\_3MHz\_QPSK\_18615\_1RB#14\_0.009~0.15\_0.009~0.1


5



Band2\_3MHz\_QPSK\_18615\_1RB#14\_0.15~30\_0.15~30




Band2\_3MHz\_QPSK\_18615\_1RB#14\_30~1000\_30~1000




Band2\_3MHz\_QPSK\_18615\_1RB#14\_1000~3000\_1000~300


0




Band2\_3MHz\_QPSK\_18615\_1RB#14\_3000~20000\_3000~20000



Band2\_3MHz\_16QAM\_18615\_1RB#14\_0.009~0.15\_0.009~0.15



Band2\_3MHz\_16QAM\_18615\_1RB#14\_0.15~30\_0.15~30



Band2\_3MHz\_16QAM\_18615\_1RB#14\_30~1000\_30~1000