







Band2_5MHz_16QAM_18900_1RB#24_1000~3000_1000~30
00




Band2_5MHz_16QAM_18900_1RB#24_3000~20000_3000~2
0000



Band2_5MHz_QPSK_18900_25RB#0_0.009~0.15_0.009~0.1
5




Band2_5MHz_QPSK_18900_25RB#0_0.15~30_0.15~30



22:25:13 08.01.2024


Band2_5MHz_QPSK_18900_25RB#0_30~1000_30~1000



22:25:25 08.01.2024


Band2_5MHz_QPSK_18900_25RB#0_1000~3000_1000~300

0



22:25:37 08.01.2024


Band2_5MHz_QPSK_18900_25RB#0_3000~20000_3000~20000




22:25:43 08.01.2024

Band2_5MHz_16QAM_18900_25RB#0_0.009~0.15_0.009~0.15


15




Band2_5MHz_16QAM_18900_25RB#0_0.15~30_0.15~30




Band2_5MHz_16QAM_18900_25RB#0_30~1000_30~1000




Band2_5MHz_16QAM_18900_25RB#0_1000~3000_1000~30
00




Band2_5MHz_16QAM_18900_25RB#0_3000~20000_3000~2
0000




Band2_5MHz_QPSK_19175_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_QPSK_19175_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_1RB#0_30~1000_30~1000




Band2_5MHz_QPSK_19175_1RB#0_1000~3000_1000~3000




Band2_5MHz_QPSK_19175_1RB#0_3000~20000_3000~20000




Band2_5MHz_16QAM_19175_1RB#0_0.009~0.15_0.009~0.15



Band2_5MHz_16QAM_19175_1RB#0_0.15~30_0.15~30




Band2_5MHz_16QAM_19175_1RB#0_30~1000_30~1000




Band2_5MHz_16QAM_19175_1RB#0_1000~3000_1000~300

0




Band2_5MHz_16QAM_19175_1RB#0_3000~20000_3000~20

000




Band2_5MHz_QPSK_19175_1RB#24_0.009~0.15_0.009~0.1


5




Band2_5MHz_QPSK_19175_1RB#24_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_1RB#24_30~1000_30~1000




Band2_5MHz_QPSK_19175_1RB#24_1000~3000_1000~300
0




Band2_5MHz_QPSK_19175_1RB#24_3000~20000_3000~20
000




Band2_5MHz_16QAM_19175_1RB#24_0.009~0.15_0.009~0.
15




Band2_5MHz_16QAM_19175_1RB#24_0.15~30_0.15~30




Band2_5MHz_16QAM_19175_1RB#24_30~1000_30~1000



Band2_5MHz_16QAM_19175_1RB#24_1000~3000_1000~30
00




Band2_5MHz_16QAM_19175_1RB#24_3000~20000_3000~2
0000




Band2_5MHz_QPSK_19175_25RB#0_0.009~0.15_0.009~0.1


5



Band2_5MHz_QPSK_19175_25RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_25RB#0_30~1000_30~1000




Band2_5MHz_QPSK_19175_25RB#0_1000~3000_1000~300


0




Band2_5MHz_QPSK_19175_25RB#0_3000~20000_3000~20000




Band2_5MHz_16QAM_19175_25RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_16QAM_19175_25RB#0_0.15~30_0.15~30




Band2_5MHz_16QAM_19175_25RB#0_30~1000_30~1000




Band2_5MHz_16QAM_19175_25RB#0_1000~3000_1000~30
00




Band2_5MHz_16QAM_19175_25RB#0_3000~20000_3000~2
0000



Band2_10MHz_QPSK_18650_1RB#0_0.009~0.15_0.009~0.1
5




Band2_10MHz_QPSK_18650_1RB#0_0.15~30_0.15~30



22:30:47 08.01.2024


Band2_10MHz_QPSK_18650_1RB#0_30~1000_30~1000



22:30:59 08.01.2024


Band2_10MHz_QPSK_18650_1RB#0_1000~3000_1000~300

0



22:31:11 08.01.2024


Band2_10MHz_QPSK_18650_1RB#0_3000~20000_3000~20000



22:31:17 08.01.2024


Band2_10MHz_16QAM_18650_1RB#0_0.009~0.15_0.009~0.15

15




22:31:22 08.01.2024

Band2_10MHz_16QAM_18650_1RB#0_0.15~30_0.15~30




22:31:27 08.01.2024

Band2_10MHz_16QAM_18650_1RB#0_30~1000_30~1000




22:31:39 08.01.2024

Band2_10MHz_16QAM_18650_1RB#0_1000~3000_1000~30
00




22:31:51 08.01.2024

Band2_10MHz_16QAM_18650_1RB#0_3000~20000_3000~2
0000




Band2_10MHz_QPSK_18650_1RB#49_0.009~0.15_0.009~0.


15



Band2_10MHz_QPSK_18650_1RB#49_0.15~30_0.15~30




Band2_10MHz_QPSK_18650_1RB#49_30~1000_30~1000




Band2_10MHz_QPSK_18650_1RB#49_1000~3000_1000~30


00




Band2_10MHz_QPSK_18650_1RB#49_3000~20000_3000~20000




Band2_10MHz_16QAM_18650_1RB#49_0.009~0.15_0.009~0.15



Band2_10MHz_16QAM_18650_1RB#49_0.15~30_0.15~30




Band2_10MHz_16QAM_18650_1RB#49_30~1000_30~1000




22:32:58 08.01.2024

Band2_10MHz_16QAM_18650_1RB#49_1000~3000_1000~3000




22:33:10 08.01.2024

Band2_10MHz_16QAM_18650_1RB#49_3000~20000_3000~20000




22:33:22 08.01.2024

Band2_10MHz_QPSK_18900_1RB#0_0.009~0.15_0.009~0.15




22:33:26 08.01.2024

Band2_10MHz_QPSK_18900_1RB#0_0.15~30_0.15~30



22:33:31 08.01.2024


Band2_10MHz_QPSK_18900_1RB#0_30~1000_30~1000



22:33:43 08.01.2024

Band2_10MHz_QPSK_18900_1RB#0_1000~3000_1000~300


0



22:33:54 08.01.2024

Band2_10MHz_QPSK_18900_1RB#0_3000~20000_3000~20


000




22:34:01 08.01.2024

Band2_10MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15


15




Band2_10MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_10MHz_16QAM_18900_1RB#0_30~1000_30~1000




Band2_10MHz_16QAM_18900_1RB#0_1000~3000_1000~3000




Band2_10MHz_16QAM_18900_1RB#0_3000~20000_3000~20000



Band2_10MHz_QPSK_18900_1RB#49_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_18900_1RB#49_0.15~30_0.15~30




22:34:50 08.01.2024

Band2_10MHz_QPSK_18900_1RB#49_30~1000_30~1000




22:35:02 08.01.2024

Band2_10MHz_QPSK_18900_1RB#49_1000~3000_1000~3000




22:35:13 08.01.2024

Band2_10MHz_QPSK_18900_1RB#49_3000~20000_3000~20000




22:35:20 08.01.2024

Band2_10MHz_16QAM_18900_1RB#49_0.009~0.15_0.009~0.15




22:35:24 08.01.2024

Band2_10MHz_16QAM_18900_1RB#49_0.15~30_0.15~30




22:35:29 08.01.2024


Band2_10MHz_16QAM_18900_1RB#49_30~1000_30~1000




Band2_10MHz_16QAM_18900_1RB#49_1000~3000_1000~3000




Band2_10MHz_16QAM_18900_1RB#49_3000~20000_3000~20000




Band2_10MHz_QPSK_19150_1RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_19150_1RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_19150_1RB#0_30~1000_30~1000




Band2_10MHz_QPSK_19150_1RB#0_1000~3000_1000~3000




Band2_10MHz_QPSK_19150_1RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_19150_1RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_16QAM_19150_1RB#0_0.15~30_0.15~30




Band2_10MHz_16QAM_19150_1RB#0_30~1000_30~1000




Band2_10MHz_16QAM_19150_1RB#0_1000~3000_1000~3000




Band2_10MHz_16QAM_19150_1RB#0_3000~20000_3000~20000




Band2_10MHz_QPSK_19150_1RB#49_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_19150_1RB#49_0.15~30_0.15~30




Band2_10MHz_QPSK_19150_1RB#49_30~1000_30~1000




Band2_10MHz_QPSK_19150_1RB#49_1000~3000_1000~3000




Band2_10MHz_QPSK_19150_1RB#49_3000~20000_3000~20000




Band2_10MHz_16QAM_19150_1RB#49_0.009~0.15_0.009~0.15




Band2_10MHz_16QAM_19150_1RB#49_0.15~30_0.15~30




Band2_10MHz_16QAM_19150_1RB#49_30~1000_30~1000




Band2_10MHz_16QAM_19150_1RB#49_1000~3000_1000~3000




Band2_10MHz_16QAM_19150_1RB#49_3000~20000_3000~20000




Band2_10MHz_QPSK_18650_50RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_18650_50RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_18650_50RB#0_30~1000_30~1000




Band2_10MHz_QPSK_18650_50RB#0_1000~3000_1000~3000




Band2_10MHz_QPSK_18650_50RB#0_3000~20000_3000~20000




Band2_10MHz_QPSK_18900_50RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_18900_50RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_18900_50RB#0_30~1000_30~1000




Band2_10MHz_QPSK_18900_50RB#0_1000~3000_1000~3000




Band2_10MHz_QPSK_18900_50RB#0_3000~20000_3000~20000




Band2_10MHz_QPSK_19150_50RB#0_0.009~0.15_0.009~0.15




Band2_10MHz_QPSK_19150_50RB#0_0.15~30_0.15~30




Band2_10MHz_QPSK_19150_50RB#0_30~1000_30~1000




Band2_10MHz_QPSK_19150_50RB#0_1000~3000_1000~3000



Band2_10MHz_QPSK_19150_50RB#0_3000~20000_3000~20000




Band2_15MHz_QPSK_18675_1RB#0_0.009~0.15_0.009~0.15




22:41:21 08.01.2024

Band2_15MHz_QPSK_18675_1RB#0_0.15~30_0.15~30



22:41:26 08.01.2024


Band2_15MHz_QPSK_18675_1RB#0_30~1000_30~1000



22:41:37 08.01.2024

Band2_15MHz_QPSK_18675_1RB#0_1000~3000_1000~3000


0



22:41:49 08.01.2024


Band2_15MHz_QPSK_18675_1RB#0_3000~20000_3000~20000

000




Band2_15MHz_16QAM_18675_1RB#0_0.009~0.15_0.009~0.


15



Band2_15MHz_16QAM_18675_1RB#0_0.15~30_0.15~30




Band2_15MHz_16QAM_18675_1RB#0_30~1000_30~1000




Band2_15MHz_16QAM_18675_1RB#0_1000~3000_1000~30

00




22:42:28 08.01.2024

Band2_15MHz_16QAM_18675_1RB#0_3000~20000_3000~20000




22:42:35 08.01.2024

Band2_15MHz_QPSK_18675_1RB#74_0.009~0.15_0.009~0.15




22:42:39 08.01.2024

Band2_15MHz_QPSK_18675_1RB#74_0.15~30_0.15~30




22:42:44 08.01.2024


Band2_15MHz_QPSK_18675_1RB#74_30~1000_30~1000




Band2_15MHz_QPSK_18675_1RB#74_1000~3000_1000~30
00



Band2_15MHz_QPSK_18675_1RB#74_3000~20000_3000~2
0000



Band2_15MHz_16QAM_18675_1RB#74_0.009~0.15_0.009~0
.15



Band2_15MHz_16QAM_18675_1RB#74_0.15~30_0.15~30