







Band12_1.4MHz_16QAM_23017_1RB#5_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23017_1RB#5_30~1000_30~1000




Band12_1.4MHz_16QAM_23017_1RB#5_1000~3000_1000~3000




Band12_1.4MHz_16QAM_23017_1RB#5_3000~10000_3000~10000




Band12_1.4MHz_QPSK_23017_6RB#0_0.009~0.15_0.009~0.15




Band12_1.4MHz_QPSK_23017_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23017_6RB#0_30~1000_30~1000




Band12_1.4MHz_QPSK_23017_6RB#0_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23017_6RB#0_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23017_6RB#0_0.009~0.15_0.009~0.15



Band12_1.4MHz_16QAM_23017_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23017_6RB#0_30~1000_30~1000




01:45:17 09.01.2024

Band12_1.4MHz_16QAM_23017_6RB#0_1000~3000_1000~3000




01:45:29 09.01.2024

Band12_1.4MHz_16QAM_23017_6RB#0_3000~10000_3000~10000




01:45:41 09.01.2024

Band12_1.4MHz_QPSK_23095_1RB#0_0.009~0.15_0.009~0.15




01:45:46 09.01.2024


Band12_1.4MHz_QPSK_23095_1RB#0_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23095_1RB#0_30~1000_30~1000




Band12_1.4MHz_QPSK_23095_1RB#0_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23095_1RB#0_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23095_1RB#0_0.009~0.15_0.009~0.15




Band12_1.4MHz_16QAM_23095_1RB#0_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23095_1RB#0_30~1000_30~1000




Band12_1.4MHz_16QAM_23095_1RB#0_1000~3000_1000~3000




Band12_1.4MHz_16QAM_23095_1RB#0_3000~10000_3000~10000




Band12_1.4MHz_QPSK_23095_1RB#5_0.009~0.15_0.009~0.15




Band12_1.4MHz_QPSK_23095_1RB#5_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23095_1RB#5_30~1000_30~1000




Band12_1.4MHz_QPSK_23095_1RB#5_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23095_1RB#5_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23095_1RB#5_0.009~0.15_0.009~0.15



Band12_1.4MHz_16QAM_23095_1RB#5_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23095_1RB#5_30~1000_30~1000




01:48:01 09.01.2024

Band12_1.4MHz_16QAM_23095_1RB#5_1000~3000_1000~3000




01:48:13 09.01.2024

Band12_1.4MHz_16QAM_23095_1RB#5_3000~10000_3000~10000




01:48:19 09.01.2024

Band12_1.4MHz_QPSK_23095_6RB#0_0.009~0.15_0.009~0.15




01:48:24 09.01.2024


Band12_1.4MHz_QPSK_23095_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23095_6RB#0_30~1000_30~1000




Band12_1.4MHz_QPSK_23095_6RB#0_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23095_6RB#0_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23095_6RB#0_0.009~0.15_0.009~0.15




Band12_1.4MHz_16QAM_23095_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23095_6RB#0_30~1000_30~1000




Band12_1.4MHz_16QAM_23095_6RB#0_1000~3000_1000~3000




Band12_1.4MHz_16QAM_23095_6RB#0_3000~10000_3000~10000




Band12_1.4MHz_QPSK_23173_1RB#0_0.009~0.15_0.009~0.15




Band12_1.4MHz_QPSK_23173_1RB#0_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23173_1RB#0_30~1000_30~1000




Band12_1.4MHz_QPSK_23173_1RB#0_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23173_1RB#0_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23173_1RB#0_0.009~0.15_0.009~0.15



Band12_1.4MHz_16QAM_23173_1RB#0_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23173_1RB#0_30~1000_30~1000




01:50:43 09.01.2024

Band12_1.4MHz_16QAM_23173_1RB#0_1000~3000_1000~3000




01:50:55 09.01.2024

Band12_1.4MHz_16QAM_23173_1RB#0_3000~10000_3000~10000




01:51:02 09.01.2024

Band12_1.4MHz_QPSK_23173_1RB#5_0.009~0.15_0.009~0.15




01:51:07 09.01.2024

Band12_1.4MHz_QPSK_23173_1RB#5_0.15~30_0.15~30




01:51:11 09.01.2024

Band12_1.4MHz_QPSK_23173_1RB#5_30~1000_30~1000




01:51:23 09.01.2024

Band12_1.4MHz_QPSK_23173_1RB#5_1000~3000_1000~3000
00




01:51:35 09.01.2024

Band12_1.4MHz_QPSK_23173_1RB#5_3000~10000_3000~10000




01:51:42 09.01.2024


Band12_1.4MHz_16QAM_23173_1RB#5_0.009~0.15_0.009~0.15




Band12_1.4MHz_16QAM_23173_1RB#5_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23173_1RB#5_30~1000_30~1000




Band12_1.4MHz_16QAM_23173_1RB#5_1000~3000_1000~3000




Band12_1.4MHz_16QAM_23173_1RB#5_3000~10000_3000~10000




Band12_1.4MHz_QPSK_23173_6RB#0_0.009~0.15_0.009~0.15




Band12_1.4MHz_QPSK_23173_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_QPSK_23173_6RB#0_30~1000_30~1000




Band12_1.4MHz_QPSK_23173_6RB#0_1000~3000_1000~3000




Band12_1.4MHz_QPSK_23173_6RB#0_3000~10000_3000~10000




Band12_1.4MHz_16QAM_23173_6RB#0_0.009~0.15_0.009~0.15



Band12_1.4MHz_16QAM_23173_6RB#0_0.15~30_0.15~30




Band12_1.4MHz_16QAM_23173_6RB#0_30~1000_30~1000




01:53:21 09.01.2024

Band12_1.4MHz_16QAM_23173_6RB#0_1000~3000_1000~3000




01:53:33 09.01.2024

Band12_1.4MHz_16QAM_23173_6RB#0_3000~10000_3000~10000




01:53:52 09.01.2024

Band12_3MHz_QPSK_23025_1RB#0_0.009~0.15_0.009~0.1




01:53:57 09.01.2024


Band12_3MHz_QPSK_23025_1RB#0_0.15~30_0.15~30




Band12_3MHz_QPSK_23025_1RB#0_30~1000_30~1000




Band12_3MHz_QPSK_23025_1RB#0_1000~3000_1000~3000




Band12_3MHz_QPSK_23025_1RB#0_3000~10000_3000~10000




Band12_3MHz_16QAM_23025_1RB#0_0.009~0.15_0.009~0.1



Band12_3MHz_16QAM_23025_1RB#0_0.15~30_0.15~30




Band12_3MHz_16QAM_23025_1RB#0_30~1000_30~1000




Band12_3MHz_16QAM_23025_1RB#0_1000~3000_1000~30

00




Band12_3MHz_16QAM_23025_1RB#0_3000~10000_3000~10

000




Band12_3MHz_QPSK_23025_1RB#14_0.009~0.15_0.009~0.


15



Band12_3MHz_QPSK_23025_1RB#14_0.15~30_0.15~30




Band12_3MHz_QPSK_23025_1RB#14_30~1000_30~1000




Band12_3MHz_QPSK_23025_1RB#14_1000~3000_1000~300


0




Band12_3MHz_QPSK_23025_1RB#14_3000~10000_3000~10000




Band12_3MHz_16QAM_23025_1RB#14_0.009~0.15_0.009~0.15




Band12_3MHz_16QAM_23025_1RB#14_0.15~30_0.15~30




Band12_3MHz_16QAM_23025_1RB#14_30~1000_30~1000




Band12_3MHz_16QAM_23025_1RB#14_1000~3000_1000~3000




Band12_3MHz_16QAM_23025_1RB#14_3000~10000_3000~10000




Band12_3MHz_QPSK_23025_15RB#0_0.009~0.15_0.009~0.15




Band12_3MHz_QPSK_23025_15RB#0_0.15~30_0.15~30




Band12_3MHz_QPSK_23025_15RB#0_30~1000_30~1000




Band12_3MHz_QPSK_23025_15RB#0_1000~3000_1000~300
0




Band12_3MHz_QPSK_23025_15RB#0_3000~10000_3000~1
0000




Band12_3MHz_16QAM_23025_15RB#0_0.009~0.15_0.009~0.
15




Band12_3MHz_16QAM_23025_15RB#0_0.15~30_0.15~30




Band12_3MHz_16QAM_23025_15RB#0_30~1000_30~1000



Band12_3MHz_16QAM_23025_15RB#0_1000~3000_1000~3000




Band12_3MHz_16QAM_23025_15RB#0_3000~10000_3000~10000




Band12_3MHz_QPSK_23095_1RB#0_0.009~0.15_0.009~0.1


5




Band12_3MHz_QPSK_23095_1RB#0_0.15~30_0.15~30



Band12_3MHz_QPSK_23095_1RB#0_30~1000_30~1000




Band12_3MHz_QPSK_23095_1RB#0_1000~3000_1000~3000




01:58:26 09.01.2024

Band12_3MHz_QPSK_23095_1RB#0_3000~10000_3000~10000




01:58:33 09.01.2024

Band12_3MHz_16QAM_23095_1RB#0_0.009~0.15_0.009~0.15




01:58:37 09.01.2024

Band12_3MHz_16QAM_23095_1RB#0_0.15~30_0.15~30




01:58:42 09.01.2024


Band12_3MHz_16QAM_23095_1RB#0_30~1000_30~1000




Band12_3MHz_16QAM_23095_1RB#0_1000~3000_1000~3000




Band12_3MHz_16QAM_23095_1RB#0_3000~10000_3000~10000




Band12_3MHz_QPSK_23095_1RB#14_0.009~0.15_0.009~0.15




Band12_3MHz_QPSK_23095_1RB#14_0.15~30_0.15~30




Band12_3MHz_QPSK_23095_1RB#14_30~1000_30~1000



Band12_3MHz_QPSK_23095_1RB#14_1000~3000_1000~300
0



Band12_3MHz_QPSK_23095_1RB#14_3000~10000_3000~1
0000



Band12_3MHz_16QAM_23095_1RB#14_0.009~0.15_0.009~0.
15