







Band26_15MHz_16QAM_26865_1RB#0



Band26_15MHz_16QAM_26865_1RB#74




Band26_15MHz_16QAM_26965_1RB#0




Band26_15MHz_16QAM_26965_1RB#74

Conducted Spurious Emission


Test Graphs




Band26_1.4MHz_QPSK_26797_1RB#0_0.009~0.15_0.009~0.15




Band26_1.4MHz_QPSK_26797_1RB#0_0.15~30_0.15~30



Band26_1.4MHz_QPSK_26797_1RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_26797_1RB#0_1000~3000_1000~3000




20:04:04 09.01.2024

Band26_1.4MHz_QPSK_26797_1RB#0_3000~10000_3000~10000




20:04:11 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#0_0.009~0.15_0.009~0.15




20:04:15 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#0_0.15~30_0.15~30




20:04:20 09.01.2024


Band26_1.4MHz_16QAM_26797_1RB#0_30~1000_30~1000




Band26_1.4MHz_16QAM_26797_1RB#0_1000~3000_1000~3000




Band26_1.4MHz_16QAM_26797_1RB#0_3000~10000_3000~10000




Band26_1.4MHz_QPSK_26797_1RB#5_0.009~0.15_0.009~0.15




Band26_1.4MHz_QPSK_26797_1RB#5_0.15~30_0.15~30




Band26_1.4MHz_QPSK_26797_1RB#5_30~1000_30~1000




Band26_1.4MHz_QPSK_26797_1RB#5_1000~3000_1000~3000
00



Band26_1.4MHz_QPSK_26797_1RB#5_3000~10000_3000~10000
0000




Band26_1.4MHz_16QAM_26797_1RB#5_0.009~0.15_0.009~0.15




20:05:34 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#5_0.15~30_0.15~30




20:05:39 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#5_30~1000_30~1000




20:05:50 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#5_1000~3000_1000~3000




20:06:02 09.01.2024

Band26_1.4MHz_16QAM_26797_1RB#5_3000~10000_3000~10000




Band26_1.4MHz_QPSK_26797_6RB#0_0.009~0.15_0.009~0.


15



Band26_1.4MHz_QPSK_26797_6RB#0_0.15~30_0.15~30




Band26_1.4MHz_QPSK_26797_6RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_26797_6RB#0_1000~3000_1000~30


00




Band26_1.4MHz_QPSK_26797_6RB#0_3000~10000_3000~10000




Band26_1.4MHz_16QAM_26797_6RB#0_0.009~0.15_0.009~0.15



Band26_1.4MHz_16QAM_26797_6RB#0_0.15~30_0.15~30




Band26_1.4MHz_16QAM_26797_6RB#0_30~1000_30~1000




20:07:09 09.01.2024

Band26_1.4MHz_16QAM_26797_6RB#0_1000~3000_1000~3000




20:07:21 09.01.2024

Band26_1.4MHz_16QAM_26797_6RB#0_3000~10000_3000~10000




20:07:33 09.01.2024

Band26_1.4MHz_QPSK_26915_1RB#0_0.009~0.15_0.009~0.15




20:07:37 09.01.2024


Band26_1.4MHz_QPSK_26915_1RB#0_0.15~30_0.15~30




Band26_1.4MHz_QPSK_26915_1RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_26915_1RB#0_1000~3000_1000~3000
00




Band26_1.4MHz_QPSK_26915_1RB#0_3000~10000_3000~10000
0000




Band26_1.4MHz_16QAM_26915_1RB#0_0.009~0.15_0.009~0.15




Band26_1.4MHz_16QAM_26915_1RB#0_0.15~30_0.15~30




Band26_1.4MHz_16QAM_26915_1RB#0_30~1000_30~1000



Band26_1.4MHz_16QAM_26915_1RB#0_1000~3000_1000~3000




Band26_1.4MHz_16QAM_26915_1RB#0_3000~10000_3000~10000




Band26_1.4MHz_QPSK_26915_1RB#5_0.009~0.15_0.009~0.


15



Band26_1.4MHz_QPSK_26915_1RB#5_0.15~30_0.15~30




Band26_1.4MHz_QPSK_26915_1RB#5_30~1000_30~1000




Band26_1.4MHz_QPSK_26915_1RB#5_1000~3000_1000~30


00




Band26_1.4MHz_QPSK_26915_1RB#5_3000~10000_3000~10000




Band26_1.4MHz_16QAM_26915_1RB#5_0.009~0.15_0.009~0.15



Band26_1.4MHz_16QAM_26915_1RB#5_0.15~30_0.15~30




Band26_1.4MHz_16QAM_26915_1RB#5_30~1000_30~1000




20:09:52 09.01.2024

Band26_1.4MHz_16QAM_26915_1RB#5_1000~3000_1000~3000




20:10:04 09.01.2024

Band26_1.4MHz_16QAM_26915_1RB#5_3000~10000_3000~10000




20:10:11 09.01.2024

Band26_1.4MHz_QPSK_26915_6RB#0_0.009~0.15_0.009~0.15




20:10:15 09.01.2024


Band26_1.4MHz_QPSK_26915_6RB#0_0.15~30_0.15~30




Band26_1.4MHz_QPSK_26915_6RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_26915_6RB#0_1000~3000_1000~3000
00




Band26_1.4MHz_QPSK_26915_6RB#0_3000~10000_3000~10000
0000




Band26_1.4MHz_16QAM_26915_6RB#0_0.009~0.15_0.009~0.15




Band26_1.4MHz_16QAM_26915_6RB#0_0.15~30_0.15~30





Band26_1.4MHz_16QAM_26915_6RB#0_30~1000_30~1000



Band26_1.4MHz_16QAM_26915_6RB#0_1000~3000_1000~3000




Band26_1.4MHz_16QAM_26915_6RB#0_3000~10000_3000~10000




Band26_1.4MHz_QPSK_27033_1RB#0_0.009~0.15_0.009~0.

15

Band26_1.4MHz_QPSK_27033_1RB#0_0.15~30_0.15~30




Band26_1.4MHz_QPSK_27033_1RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_27033_1RB#0_1000~3000_1000~30


00




Band26_1.4MHz_QPSK_27033_1RB#0_3000~10000_3000~10000




Band26_1.4MHz_16QAM_27033_1RB#0_0.009~0.15_0.009~0.15



Band26_1.4MHz_16QAM_27033_1RB#0_0.15~30_0.15~30




Band26_1.4MHz_16QAM_27033_1RB#0_30~1000_30~1000




20:12:35 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#0_1000~3000_1000~3000




20:12:47 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#0_3000~10000_3000~10000




20:12:53 09.01.2024

Band26_1.4MHz_QPSK_27033_1RB#5_0.009~0.15_0.009~0.15




20:12:58 09.01.2024


Band26_1.4MHz_QPSK_27033_1RB#5_0.15~30_0.15~30




Band26_1.4MHz_QPSK_27033_1RB#5_30~1000_30~1000




Band26_1.4MHz_QPSK_27033_1RB#5_1000~3000_1000~3000



Band26_1.4MHz_QPSK_27033_1RB#5_3000~10000_3000~10000




Band26_1.4MHz_16QAM_27033_1RB#5_0.009~0.15_0.009~0.15




20:13:38 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#5_0.15~30_0.15~30




20:13:42 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#5_30~1000_30~1000




20:13:54 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#5_1000~3000_1000~3000




20:14:06 09.01.2024

Band26_1.4MHz_16QAM_27033_1RB#5_3000~10000_3000~10000




Band26_1.4MHz_QPSK_27033_6RB#0_0.009~0.15_0.009~0.


15



Band26_1.4MHz_QPSK_27033_6RB#0_0.15~30_0.15~30




Band26_1.4MHz_QPSK_27033_6RB#0_30~1000_30~1000




Band26_1.4MHz_QPSK_27033_6RB#0_1000~3000_1000~30


00




Band26_1.4MHz_QPSK_27033_6RB#0_3000~10000_3000~10000




Band26_1.4MHz_16QAM_27033_6RB#0_0.009~0.15_0.009~0.15



Band26_1.4MHz_16QAM_27033_6RB#0_0.15~30_0.15~30




Band26_1.4MHz_16QAM_27033_6RB#0_30~1000_30~1000




20:15:13 09.01.2024

Band26_1.4MHz_16QAM_27033_6RB#0_1000~3000_1000~3000




20:15:25 09.01.2024

Band26_1.4MHz_16QAM_27033_6RB#0_3000~10000_3000~10000




20:16:03 09.01.2024

Band26_3MHz_QPSK_26805_1RB#0_0.009~0.15_0.009~0.15




20:16:08 09.01.2024

Band26_3MHz_QPSK_26805_1RB#0_0.15~30_0.15~30




Band26_3MHz_QPSK_26805_1RB#0_30~1000_30~1000




Band26_3MHz_QPSK_26805_1RB#0_1000~3000_1000~300

0




Band26_3MHz_QPSK_26805_1RB#0_3000~10000_3000~10000




Band26_3MHz_16QAM_26805_1RB#0_0.009~0.15_0.009~0.15


15




Band26_3MHz_16QAM_26805_1RB#0_0.15~30_0.15~30




Band26_3MHz_16QAM_26805_1RB#0_30~1000_30~1000



Band26_3MHz_16QAM_26805_1RB#0_1000~3000_1000~3000




Band26_3MHz_16QAM_26805_1RB#0_3000~10000_3000~10000




Band26_3MHz_QPSK_26805_1RB#14_0.009~0.15_0.009~0.


15



Band26_3MHz_QPSK_26805_1RB#14_0.15~30_0.15~30




Band26_3MHz_QPSK_26805_1RB#14_30~1000_30~1000




Band26_3MHz_QPSK_26805_1RB#14_1000~3000_1000~30


00




Band26_3MHz_QPSK_26805_1RB#14_3000~10000_3000~10000




Band26_3MHz_16QAM_26805_1RB#14_0.009~0.15_0.009~0.15



Band26_3MHz_16QAM_26805_1RB#14_0.15~30_0.15~30




Band26_3MHz_16QAM_26805_1RB#14_30~1000_30~1000




20:18:23 09.01.2024

Band26_3MHz_16QAM_26805_1RB#14_1000~3000_1000~3000




20:18:35 09.01.2024

Band26_3MHz_16QAM_26805_1RB#14_3000~10000_3000~10000




20:18:41 09.01.2024

Band26_3MHz_QPSK_26805_15RB#0_0.009~0.15_0.009~0.15




20:18:45 09.01.2024


Band26_3MHz_QPSK_26805_15RB#0_0.15~30_0.15~30




Band26_3MHz_QPSK_26805_15RB#0_30~1000_30~1000



Band26_3MHz_QPSK_26805_15RB#0_1000~3000_1000~3000



Band26_3MHz_QPSK_26805_15RB#0_3000~10000_3000~10000



Band26_3MHz_16QAM_26805_15RB#0_0.009~0.15_0.009~0.15