



LTE Band 7, Normal


20MHz_Low_QPSK_1@0




20MHz_Low_QPSK_100@0




20MHz_Low_16QAM_1@0




20MHz_Low_16QAM_100@0




20MHz_Middle_QPSK_1@0



20MHz_Middle_QPSK_100@0




20MHz_Middle_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:12:41

20MHz_Middle_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:12:56

20MHz_High_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:13:11

20MHz_High_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:13:25

20MHz_High_16QAM_1@0



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:13:40


20MHz_High_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 18.DEC.2024 11:13:54

LTE Band 12, Normal


10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_50@0




10MHz_Middle_QPSK_1@0




10MHz_Middle_QPSK_50@0




10MHz_Middle_16QAM_1@0




10MHz_Middle_16QAM_50@0




10MHz_High_QPSK_1@0




10MHz_High_QPSK_50@0



10MHz_High_16QAM_1@0




10MHz_High_16QAM_50@0




LTE Band 13, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0



5MHz_High_QPSK_1@0





5MHz_High_QPSK_25@0





5MHz_High_16QAM_1@0

5MHz_High_16QAM_25@0





10MHz_Middle_QPSK_1@0

10MHz_Middle_QPSK_50@0




10MHz_Middle_16QAM_1@0

10MHz_Middle_16QAM_50@0




LTE Band 17, Normal


10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0




10MHz_Low_16QAM_50@0




10MHz_Middle_QPSK_1@0




10MHz_Middle_QPSK_50@0




10MHz_Middle_16QAM_1@0




10MHz_Middle_16QAM_50@0




10MHz_High_QPSK_1@0




10MHz_High_QPSK_50@0



10MHz_High_16QAM_1@0



10MHz_High_16QAM_50@0




Out of band emission,Band Edge


FCC Part 22H

LTE Band 5, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:54:39




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:55:24

3MHz_Low_QPSK_1@0

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:57:24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:58:16

3MHz_Low_16QAM_1@0

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:59:08




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:59:59

3MHz_High_QPSK_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 10:00:59

3MHz_High_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 10:01:51

3MHz_High_16QAM_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:21:35

3MHz_High_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:22:26

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:25:11

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:26:25

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:27:20

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:28:14

5MHz_High_QPSK_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:29:17

5MHz_High_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:30:11

5MHz_High_16QAM_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:31:05

5MHz_High_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:31:59

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:35:12

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:36:26

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:37:41

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:38:55

10MHz_High_QPSK_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:40:16

10MHz_High_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:41:30

10MHz_High_16QAM_1@49



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:42:44

10MHz_High_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 14:43:59


FCC Part 24E

LTE Band 2, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 08:59:28




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 08:59:51

3MHz_Low_QPSK_1@0

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:01:24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:01:51

3MHz_Low_16QAM_1@0

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:02:17




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:02:44

3MHz_High_QPSK_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:03:20

3MHz_High_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:03:47

3MHz_High_16QAM_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:04:14

3MHz_High_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:04:42

5MHz_Low_QPSK_1@0



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:06:18


5MHz_Low_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:06:43

5MHz_Low_16QAM_1@0

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:07:08




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:07:34

5MHz_High_QPSK_1@24

5MHz_High_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:08:08




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:08:33

5MHz_High_16QAM_1@24

5MHz_High_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:08:57




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:09:22

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:11:04

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:11:39

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:12:13

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:12:48

10MHz_High_QPSK_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:13:31

10MHz_High_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:14:06

10MHz_High_16QAM_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:14:42

10MHz_High_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:15:17

15MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:34:11

15MHz_Low_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:34:54

15MHz_Low_16QAM_1@0



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:35:38

15MHz_Low_16QAM_75@0



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:36:22