



15MHz_High_QPSK_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:37:13

15MHz_High_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:37:57

15MHz_High_16QAM_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:38:41

15MHz_High_16QAM_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:39:25

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:41:30

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:42:25

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:43:20

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:44:15

20MHz_High_QPSK_1@99




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:45:19

20MHz_High_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:46:14

20MHz_High_16QAM_1@99



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:47:09


20MHz_High_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 09:48:03

LTE Band 25, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0



1.4MHz_High_QPSK_1@5




1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 23.APR.2025 14:07:12




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 16:56:36

3MHz_Low_QPSK_1@0

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 16:59:10




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 16:59:38

3MHz_Low_16QAM_1@0

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:00:05




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:00:31

3MHz_High_QPSK_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:01:05

3MHz_High_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:01:31

3MHz_High_16QAM_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:01:57

3MHz_High_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:02:23

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:05:00

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:05:23

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:05:47

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:06:11

5MHz_High_QPSK_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:06:42

5MHz_High_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:07:06

5MHz_High_16QAM_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:07:30

5MHz_High_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:07:53

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:10:53

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:11:28

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:12:03

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:12:38

10MHz_High_QPSK_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:13:21

10MHz_High_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:13:55

10MHz_High_16QAM_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:14:30

10MHz_High_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:15:05

15MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:18:03

15MHz_Low_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:18:48

15MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:19:32

15MHz_Low_16QAM_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:20:16

15MHz_High_QPSK_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:21:07

15MHz_High_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:21:51

15MHz_High_16QAM_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:22:35

15MHz_High_16QAM_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:23:19

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:26:39

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:27:32

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:28:27

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:29:21

20MHz_High_QPSK_1@99




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:30:23

20MHz_High_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:31:18

20MHz_High_16QAM_1@99



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:32:12

20MHz_High_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 16.DEC.2024 17:33:07


FCC Part 27

LTE Band 4, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:44:11

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:44:34

3MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:46:39

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:47:05

3MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:47:31

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:47:57

3MHz_High_QPSK_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:48:31

3MHz_High_QPSK_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:48:57

3MHz_High_16QAM_1@14




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:49:22

3MHz_High_16QAM_15@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:49:48

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:51:47

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:52:10

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:52:34

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:52:58

5MHz_High_QPSK_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:53:29

5MHz_High_QPSK_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:53:53

5MHz_High_16QAM_1@24




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:54:17

5MHz_High_16QAM_25@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:54:41

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:57:38

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:58:12

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:58:46

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 12:59:21

10MHz_High_QPSK_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:00:02

10MHz_High_QPSK_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:00:37

10MHz_High_16QAM_1@49




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:01:12

10MHz_High_16QAM_50@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:01:46

15MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:04:52

15MHz_Low_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:05:36

15MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:06:20

15MHz_Low_16QAM_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:07:04

15MHz_High_QPSK_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:07:58

15MHz_High_QPSK_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 13:08:42

15MHz_High_16QAM_1@74




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:28:15

15MHz_High_16QAM_75@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:28:58

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:32:39

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:33:34

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:34:29

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:35:24

20MHz_High_QPSK_1@99




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:36:28

20MHz_High_QPSK_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:37:23

20MHz_High_16QAM_1@99



ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:38:17


20MHz_High_16QAM_100@0




ProjectNo.:2402Z58130E-RF Tester:Loge Long
Date: 17.DEC.2024 14:39:12

LTE Band 7, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0



5MHz_Low_16QAM_25@0



5MHz_High_QPSK_1@24



5MHz_High_QPSK_25@0

