



10MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:34:30

10MHz\_Low\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:52:28

10MHz\_Low\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:34:58

10MHz\_Low\_QPSK\_50@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:52:41

10MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:35:25

10MHz\_Middle\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:52:54

10MHz\_Middle\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:35:53

10MHz\_Middle\_QPSK\_50@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:53:07

10MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:36:21

10MHz\_High\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:53:20

10MHz\_High\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:36:49

10MHz\_High\_QPSK\_50@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:53:33

15MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:37:45

15MHz\_Low\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:55:08

15MHz\_Low\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:38:14

15MHz\_Low\_QPSK\_75@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:55:21

15MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:38:44

15MHz\_Middle\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:55:35

15MHz\_Middle\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:39:13

15MHz\_Middle\_QPSK\_75@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:55:49

15MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:39:41

15MHz\_High\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:56:02

15MHz\_High\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:40:10

15MHz\_High\_QPSK\_75@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:56:17

20MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:41:08

20MHz\_Low\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:56:39

20MHz\_Low\_QPSK\_100@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:41:36

20MHz\_Low\_QPSK\_100@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:56:52

20MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:42:04

20MHz\_Middle\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:57:05

20MHz\_Middle\_QPSK\_100@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:42:31

20MHz\_Middle\_QPSK\_100@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:57:20

20MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:43:01

20MHz\_High\_QPSK\_1@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:57:33

20MHz\_High\_QPSK\_100@0(30MHz~1GHz)



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 29.JUL.2025 16:43:30

20MHz\_High\_QPSK\_100@0(1GHz~18.55GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 8.AUG.2025 15:57:53

LTE Band 7, Normal


1RB was the worst case

5MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:27:55

5MHz\_Low\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:28:14

5MHz\_Low\_QPSK\_25@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:28:31

5MHz\_Low\_QPSK\_25@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:28:50

5MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:29:07

5MHz\_Middle\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:29:25

5MHz\_Middle\_QPSK\_25@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:29:41

5MHz\_Middle\_QPSK\_25@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:30:00

5MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:30:16

5MHz\_High\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:30:35

5MHz\_High\_QPSK\_25@0(30MHz~1GHz)



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:30:50


5MHz\_High\_QPSK\_25@0(1GHz~26.7GHz)



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:31:09




10MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:31:28

10MHz\_Low\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:31:47

10MHz\_Low\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:32:03

10MHz\_Low\_QPSK\_50@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:32:23

10MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:32:18

10MHz\_Middle\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:32:58

10MHz\_Middle\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:33:15

10MHz\_Middle\_QPSK\_50@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:33:34

10MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:33:50

10MHz\_High\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:34:09

10MHz\_High\_QPSK\_50@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:34:26

10MHz\_High\_QPSK\_50@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:34:45

15MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:35:11

15MHz\_Low\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:35:31

15MHz\_Low\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:39:31

15MHz\_Low\_QPSK\_75@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:39:51

15MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:40:09

15MHz\_Middle\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:40:28

15MHz\_Middle\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:40:48

15MHz\_Middle\_QPSK\_75@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:41:07

15MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:41:25

15MHz\_High\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:41:44

15MHz\_High\_QPSK\_75@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:42:03

15MHz\_High\_QPSK\_75@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:42:22

20MHz\_Low\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:42:51

20MHz\_Low\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:43:11

20MHz\_Low\_QPSK\_100@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:43:30

20MHz\_Low\_QPSK\_100@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:43:50

20MHz\_Middle\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:44:08

20MHz\_Middle\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:44:28

20MHz\_Middle\_QPSK\_100@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:44:48

20MHz\_Middle\_QPSK\_100@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:45:07

20MHz\_High\_QPSK\_1@0(30MHz~1GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:45:29

20MHz\_High\_QPSK\_1@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:45:50

20MHz\_High\_QPSK\_100@0(30MHz~1GHz)



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:46:11

20MHz\_High\_QPSK\_100@0(1GHz~26.7GHz)




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:46:31

Out of band emission,Band Edge


FCC Part 24E

LTE Band 2, Normal


1.4MHz\_Low\_QPSK\_1@0




1.4MHz\_Low\_QPSK\_6@0




1.4MHz\_Low\_16QAM\_1@0




1.4MHz\_Low\_16QAM\_6@0




1.4MHz\_High\_QPSK\_1@5



1.4MHz\_High\_QPSK\_6@0




1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:55:45

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:56:16

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:57:20

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:57:55

3MHz\_Low\_16QAM\_1@0



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:58:46


3MHz\_Low\_16QAM\_15@0



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 14:59:21




3MHz\_High\_QPSK\_1@14




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:00:11

3MHz\_High\_QPSK\_15@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:00:46

3MHz\_High\_16QAM\_1@14




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:01:37

3MHz\_High\_16QAM\_15@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:02:12

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:03:19

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:03:52

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:04:47

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:05:21

5MHz\_High\_QPSK\_1@24




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:06:16

5MHz\_High\_QPSK\_25@0




ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:06:49

5MHz\_High\_16QAM\_1@24



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:07:44

5MHz\_High\_16QAM\_25@0



ProjectNo.:2504U66843E-RF Tester:Benny Li  
Date: 27.JUL.2025 15:08:18