






Band66-5MHz-QPSK-131997-6-0-Low--25.81-PASS



Band66-5MHz-QPSK-132647-6-0-High--18.09-PASS



Band66-5MHz-16QAM-131997-6-0-Low--26.15-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-16QAM-132647-6-0-High--19.08-PASS



Band66-10MHz-QPSK-132022-6-0-Low--26.98-PASS



Band66-10MHz-QPSK-132622-6-0-High--20.33-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-10MHz-16QAM-132022-6-0-Low--27.15-PASS



Band66-10MHz-16QAM-132622-6-0-High--18.50-PASS



Band66-15MHz-QPSK-132047-6-0-Low--27.20-PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-15MHz-QPSK-132597-6-0-High--18.64-PASS



Band66-15MHz-16QAM-132047-6-0-Low--26.78-PASS



Band66-15MHz-16QAM-132597-6-0-High--18.73-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-20MHz-QPSK-132072-6-0-Low--26.66-PASS



Band66-20MHz-QPSK-132572-6-0-High--24.47-PASS



Band66-20MHz-16QAM-132072-6-0-Low--27.96-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



K.5 Conducted Spurious Emission for M1

Test Result

Band	Bandwidth	Modulation	Channel	RB Size	RB Start	NB Index	Start Freq	Stop Freq	Result (dBm)	Verdict
Band66	1.4MHz	131979	QPSK	1	0	Low	30	1000	-34.45	PASS
Band66	1.4MHz	131979	QPSK	1	0	Low	1000	5000	-33.86	PASS
Band66	1.4MHz	131979	QPSK	1	0	Low	5000	12000	-56.84	PASS
Band66	1.4MHz	131979	QPSK	1	0	Low	12000	26500	-41.67	PASS
Band66	1.4MHz	132322	QPSK	1	0	Low	30	1000	-34.95	PASS
Band66	1.4MHz	132322	QPSK	1	0	Low	1000	5000	-33.55	PASS
Band66	1.4MHz	132322	QPSK	1	0	Low	5000	12000	-56.75	PASS
Band66	1.4MHz	132322	QPSK	1	0	Low	12000	26500	-41.65	PASS
Band66	1.4MHz	132665	QPSK	1	0	High	30	1000	-34.27	PASS
Band66	1.4MHz	132665	QPSK	1	0	High	1000	5000	-40.73	PASS
Band66	1.4MHz	132665	QPSK	1	0	High	5000	12000	-56.79	PASS
Band66	1.4MHz	132665	QPSK	1	0	High	12000	26500	-41.64	PASS
Band66	1.4MHz	131979	16QAM	1	0	Low	30	1000	-34.91	PASS
Band66	1.4MHz	131979	16QAM	1	0	Low	1000	5000	-34.31	PASS
Band66	1.4MHz	131979	16QAM	1	0	Low	5000	12000	-56.51	PASS
Band66	1.4MHz	131979	16QAM	1	0	Low	12000	26500	-41.84	PASS
Band66	1.4MHz	132322	16QAM	1	0	Low	30	1000	-33.97	PASS
Band66	1.4MHz	132322	16QAM	1	0	Low	1000	5000	-34.09	PASS
Band66	1.4MHz	132322	16QAM	1	0	Low	5000	12000	-56.79	PASS
Band66	1.4MHz	132322	16QAM	1	0	Low	12000	26500	-41.63	PASS
Band66	1.4MHz	132665	16QAM	1	0	High	30	1000	-34.6	PASS
Band66	1.4MHz	132665	16QAM	1	0	High	1000	5000	-41.04	PASS
Band66	1.4MHz	132665	16QAM	1	0	High	5000	12000	-56.76	PASS
Band66	1.4MHz	132665	16QAM	1	0	High	12000	26500	-41.84	PASS
Band66	3MHz	131987	QPSK	1	0	Low	30	1000	-34.66	PASS
Band66	3MHz	131987	QPSK	1	0	Low	1000	5000	-34.13	PASS
Band66	3MHz	131987	QPSK	1	0	Low	5000	12000	-56.67	PASS
Band66	3MHz	131987	QPSK	1	0	Low	12000	26500	-41.71	PASS
Band66	3MHz	132322	QPSK	1	0	Low	30	1000	-34	PASS
Band66	3MHz	132322	QPSK	1	0	Low	1000	5000	-33.24	PASS
Band66	3MHz	132322	QPSK	1	0	Low	5000	12000	-56.65	PASS
Band66	3MHz	132322	QPSK	1	0	Low	12000	26500	-41.45	PASS
Band66	3MHz	132657	QPSK	1	0	High	30	1000	-34.33	PASS
Band66	3MHz	132657	QPSK	1	0	High	1000	5000	-40.87	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band66	3MHz	132657	QPSK	1	0	High	5000	12000	-56.63	PASS
Band66	3MHz	132657	QPSK	1	0	High	12000	26500	-41.58	PASS
Band66	3MHz	131987	16QAM	1	0	Low	30	1000	-34.47	PASS
Band66	3MHz	131987	16QAM	1	0	Low	1000	5000	-34.72	PASS
Band66	3MHz	131987	16QAM	1	0	Low	5000	12000	-56.72	PASS
Band66	3MHz	131987	16QAM	1	0	Low	12000	26500	-41.66	PASS
Band66	3MHz	132322	16QAM	1	0	Low	30	1000	-35.1	PASS
Band66	3MHz	132322	16QAM	1	0	Low	1000	5000	-34.18	PASS
Band66	3MHz	132322	16QAM	1	0	Low	5000	12000	-56.69	PASS
Band66	3MHz	132322	16QAM	1	0	Low	12000	26500	-41.68	PASS
Band66	3MHz	132657	16QAM	1	0	High	30	1000	-35.02	PASS
Band66	3MHz	132657	16QAM	1	0	High	1000	5000	-40.91	PASS
Band66	3MHz	132657	16QAM	1	0	High	5000	12000	-56.49	PASS
Band66	3MHz	132657	16QAM	1	0	High	12000	26500	-41.45	PASS
Band66	5MHz	131997	QPSK	1	0	Low	30	1000	-34.87	PASS
Band66	5MHz	131997	QPSK	1	0	Low	1000	5000	-34.07	PASS
Band66	5MHz	131997	QPSK	1	0	Low	5000	12000	-56.77	PASS
Band66	5MHz	131997	QPSK	1	0	Low	12000	26500	-41.46	PASS
Band66	5MHz	132322	QPSK	1	0	Low	30	1000	-34.81	PASS
Band66	5MHz	132322	QPSK	1	0	Low	1000	5000	-33.43	PASS
Band66	5MHz	132322	QPSK	1	0	Low	5000	12000	-56.67	PASS
Band66	5MHz	132322	QPSK	1	0	Low	12000	26500	-41.75	PASS
Band66	5MHz	132647	QPSK	1	0	High	30	1000	-34.28	PASS
Band66	5MHz	132647	QPSK	1	0	High	1000	5000	-40.91	PASS
Band66	5MHz	132647	QPSK	1	0	High	5000	12000	-56.67	PASS
Band66	5MHz	132647	QPSK	1	0	High	12000	26500	-41.48	PASS
Band66	5MHz	131997	16QAM	1	0	Low	30	1000	-34.66	PASS
Band66	5MHz	131997	16QAM	1	0	Low	1000	5000	-39.25	PASS
Band66	5MHz	131997	16QAM	1	0	Low	5000	12000	-56.78	PASS
Band66	5MHz	131997	16QAM	1	0	Low	12000	26500	-41.61	PASS
Band66	5MHz	132322	16QAM	1	0	Low	30	1000	-34.88	PASS
Band66	5MHz	132322	16QAM	1	0	Low	1000	5000	-33.42	PASS
Band66	5MHz	132322	16QAM	1	0	Low	5000	12000	-56.59	PASS
Band66	5MHz	132322	16QAM	1	0	Low	12000	26500	-41.77	PASS
Band66	5MHz	132647	16QAM	1	0	High	30	1000	-34.61	PASS
Band66	5MHz	132647	16QAM	1	0	High	1000	5000	-40.86	PASS
Band66	5MHz	132647	16QAM	1	0	High	5000	12000	-56.77	PASS
Band66	5MHz	132647	16QAM	1	0	High	12000	26500	-41.55	PASS
Band66	10MHz	132022	QPSK	1	0	Low	30	1000	-34.81	PASS
Band66	10MHz	132022	QPSK	1	0	Low	1000	5000	-33.83	PASS
Band66	10MHz	132022	QPSK	1	0	Low	5000	12000	-56.72	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band66	10MHz	132022	QPSK	1	0	Low	12000	26500	-41.67	PASS
Band66	10MHz	132322	QPSK	1	0	Low	30	1000	-34.8	PASS
Band66	10MHz	132322	QPSK	1	0	Low	1000	5000	-33.56	PASS
Band66	10MHz	132322	QPSK	1	0	Low	5000	12000	-56.67	PASS
Band66	10MHz	132322	QPSK	1	0	Low	12000	26500	-41.7	PASS
Band66	10MHz	132622	QPSK	1	0	High	30	1000	-34.9	PASS
Band66	10MHz	132622	QPSK	1	0	High	1000	5000	-40.77	PASS
Band66	10MHz	132622	QPSK	1	0	High	5000	12000	-56.51	PASS
Band66	10MHz	132622	QPSK	1	0	High	12000	26500	-41.58	PASS
Band66	10MHz	132022	16QAM	1	0	Low	30	1000	-35.13	PASS
Band66	10MHz	132022	16QAM	1	0	Low	1000	5000	-34.16	PASS
Band66	10MHz	132022	16QAM	1	0	Low	5000	12000	-56.69	PASS
Band66	10MHz	132022	16QAM	1	0	Low	12000	26500	-41.29	PASS
Band66	10MHz	132322	16QAM	1	0	Low	30	1000	-34.05	PASS
Band66	10MHz	132322	16QAM	1	0	Low	1000	5000	-33.19	PASS
Band66	10MHz	132322	16QAM	1	0	Low	5000	12000	-56.68	PASS
Band66	10MHz	132322	16QAM	1	0	Low	12000	26500	-41.65	PASS
Band66	10MHz	132622	16QAM	1	0	High	30	1000	-34.19	PASS
Band66	10MHz	132622	16QAM	1	0	High	1000	5000	-40.82	PASS
Band66	10MHz	132622	16QAM	1	0	High	5000	12000	-56.7	PASS
Band66	10MHz	132622	16QAM	1	0	High	12000	26500	-41.36	PASS
Band66	15MHz	132047	QPSK	1	0	Low	30	1000	-34.66	PASS
Band66	15MHz	132047	QPSK	1	0	Low	1000	5000	-33.88	PASS
Band66	15MHz	132047	QPSK	1	0	Low	5000	12000	-56.55	PASS
Band66	15MHz	132047	QPSK	1	0	Low	12000	26500	-41.71	PASS
Band66	15MHz	132322	QPSK	1	0	Low	30	1000	-35.03	PASS
Band66	15MHz	132322	QPSK	1	0	Low	1000	5000	-33.52	PASS
Band66	15MHz	132322	QPSK	1	0	Low	5000	12000	-56.69	PASS
Band66	15MHz	132322	QPSK	1	0	Low	12000	26500	-41.57	PASS
Band66	15MHz	132597	QPSK	1	0	High	30	1000	-35.03	PASS
Band66	15MHz	132597	QPSK	1	0	High	1000	5000	-41.01	PASS
Band66	15MHz	132597	QPSK	1	0	High	5000	12000	-56.53	PASS
Band66	15MHz	132597	QPSK	1	0	High	12000	26500	-41.63	PASS
Band66	15MHz	132047	16QAM	1	0	Low	30	1000	-34.67	PASS
Band66	15MHz	132047	16QAM	1	0	Low	1000	5000	-34.59	PASS
Band66	15MHz	132047	16QAM	1	0	Low	5000	12000	-56.66	PASS
Band66	15MHz	132047	16QAM	1	0	Low	12000	26500	-41.67	PASS
Band66	15MHz	132322	16QAM	1	0	Low	30	1000	-34.59	PASS
Band66	15MHz	132322	16QAM	1	0	Low	1000	5000	-32.73	PASS
Band66	15MHz	132322	16QAM	1	0	Low	5000	12000	-56.68	PASS
Band66	15MHz	132322	16QAM	1	0	Low	12000	26500	-41.55	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band66	15MHz	132597	16QAM	1	0	High	30	1000	-34.55	PASS
Band66	15MHz	132597	16QAM	1	0	High	1000	5000	-40.88	PASS
Band66	15MHz	132597	16QAM	1	0	High	5000	12000	-56.65	PASS
Band66	15MHz	132597	16QAM	1	0	High	12000	26500	-41.7	PASS
Band66	20MHz	132072	QPSK	1	0	Low	30	1000	-33.97	PASS
Band66	20MHz	132072	QPSK	1	0	Low	1000	5000	-34	PASS
Band66	20MHz	132072	QPSK	1	0	Low	5000	12000	-56.62	PASS
Band66	20MHz	132072	QPSK	1	0	Low	12000	26500	-41.54	PASS
Band66	20MHz	132322	QPSK	1	0	Low	30	1000	-34.03	PASS
Band66	20MHz	132322	QPSK	1	0	Low	1000	5000	-33.36	PASS
Band66	20MHz	132322	QPSK	1	0	Low	5000	12000	-56.71	PASS
Band66	20MHz	132322	QPSK	1	0	Low	12000	26500	-41.74	PASS
Band66	20MHz	132572	QPSK	1	0	High	30	1000	-33.75	PASS
Band66	20MHz	132572	QPSK	1	0	High	1000	5000	-40.74	PASS
Band66	20MHz	132572	QPSK	1	0	High	5000	12000	-56.36	PASS
Band66	20MHz	132572	QPSK	1	0	High	12000	26500	-41.71	PASS
Band66	20MHz	132072	16QAM	1	0	Low	30	1000	-34.33	PASS
Band66	20MHz	132072	16QAM	1	0	Low	1000	5000	-33.86	PASS
Band66	20MHz	132072	16QAM	1	0	Low	5000	12000	-56.62	PASS
Band66	20MHz	132072	16QAM	1	0	Low	12000	26500	-41.7	PASS
Band66	20MHz	132322	16QAM	1	0	Low	30	1000	-34.41	PASS
Band66	20MHz	132322	16QAM	1	0	Low	1000	5000	-33.5	PASS
Band66	20MHz	132322	16QAM	1	0	Low	5000	12000	-56.72	PASS
Band66	20MHz	132322	16QAM	1	0	Low	12000	26500	-41.81	PASS
Band66	20MHz	132572	16QAM	1	0	High	30	1000	-34.81	PASS
Band66	20MHz	132572	16QAM	1	0	High	1000	5000	-40.95	PASS
Band66	20MHz	132572	16QAM	1	0	High	5000	12000	-56.54	PASS
Band66	20MHz	132572	16QAM	1	0	High	12000	26500	-41.48	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Test Graphs



Band66-1.4MHz-QPSK-131979-1-0-Low-30-1000--34.45-PASS



Band66-1.4MHz-QPSK-131979-1-0-Low-1000-5000--33.86-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-QPSK-131979-1-0-Low-5000-12000--56.84-PASS



Band66-1.4MHz-QPSK-131979-1-0-Low-12000-26500--41.67-PASS



Band66-1.4MHz-QPSK-132322-1-0-Low-30-1000--34.95-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-QPSK-132322-1-0-Low-1000-5000--33.55-PASS



Band66-1.4MHz-QPSK-132322-1-0-Low-5000-12000--56.75-PASS



Band66-1.4MHz-QPSK-132322-1-0-Low-12000-26500--41.65-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-QPSK-132665-1-0-High-30-1000--34.27-PASS



Band66-1.4MHz-QPSK-132665-1-0-High-1000-5000--40.73-PASS



Band66-1.4MHz-QPSK-132665-1-0-High-5000-12000--56.79-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-QPSK-132665-1-0-High-12000-26500--41.64-PASS



Band66-1.4MHz-16QAM-131979-1-0-Low-30-1000--34.91-PASS



Band66-1.4MHz-16QAM-131979-1-0-Low-1000-5000--34.31-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-16QAM-131979-1-0-Low-5000-12000--56.51-PASS



Band66-1.4MHz-16QAM-131979-1-0-Low-12000-26500--41.84-PASS



Band66-1.4MHz-16QAM-132322-1-0-Low-30-1000--33.97-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-16QAM-132322-1-0-Low-1000-5000--34.09-PASS



Band66-1.4MHz-16QAM-132322-1-0-Low-5000-12000--56.79-PASS



Band66-1.4MHz-16QAM-132322-1-0-Low-12000-26500--41.63-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-16QAM-132665-1-0-High-30-1000--34.6-PASS



Band66-1.4MHz-16QAM-132665-1-0-High-1000-5000--41.04-PASS



Band66-1.4MHz-16QAM-132665-1-0-High-5000-12000--56.76-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-1.4MHz-16QAM-132665-1-0-High-12000-26500--41.84-PASS



Band66-3MHz-QPSK-131987-1-0-Low-30-1000--34.66-PASS



Band66-3MHz-QPSK-131987-1-0-Low-1000-5000--34.13-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-QPSK-131987-1-0-Low-5000-12000--56.67-PASS



Band66-3MHz-QPSK-131987-1-0-Low-12000-26500--41.71-PASS



Band66-3MHz-QPSK-132322-1-0-Low-30-1000--34-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-QPSK-132322-1-0-Low-1000-5000--33.24-PASS



Band66-3MHz-QPSK-132322-1-0-Low-5000-12000--56.65-PASS



Band66-3MHz-QPSK-132322-1-0-Low-12000-26500--41.45-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-QPSK-132657-1-0-High-30-1000--34.33-PASS



Band66-3MHz-QPSK-132657-1-0-High-1000-5000--40.87-PASS



Band66-3MHz-QPSK-132657-1-0-High-5000-12000--56.63-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-QPSK-132657-1-0-High-12000-26500--41.58-PASS



Band66-3MHz-16QAM-131987-1-0-Low-30-1000--34.47-PASS



Band66-3MHz-16QAM-131987-1-0-Low-1000-5000--34.72-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-16QAM-131987-1-0-Low-5000-12000--56.72-PASS



Band66-3MHz-16QAM-131987-1-0-Low-12000-26500--41.66-PASS



Band66-3MHz-16QAM-132322-1-0-Low-30-1000--35.1-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-16QAM-132322-1-0-Low-1000-5000--34.18-PASS



Band66-3MHz-16QAM-132322-1-0-Low-5000-12000--56.69-PASS



Band66-3MHz-16QAM-132322-1-0-Low-12000-26500--41.68-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-16QAM-132657-1-0-High-30-1000--35.02-PASS



Band66-3MHz-16QAM-132657-1-0-High-1000-5000--40.91-PASS



Band66-3MHz-16QAM-132657-1-0-High-5000-12000--56.49-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-3MHz-16QAM-132657-1-0-High-12000-26500--41.45-PASS



Band66-5MHz-QPSK-131997-1-0-Low-30-1000--34.87-PASS



Band66-5MHz-QPSK-131997-1-0-Low-1000-5000--34.07-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-QPSK-131997-1-0-Low-5000-12000--56.77-PASS



Band66-5MHz-QPSK-131997-1-0-Low-12000-26500--41.46-PASS



Band66-5MHz-QPSK-132322-1-0-Low-30-1000--34.81-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-QPSK-132322-1-0-Low-1000-5000--33.43-PASS



Band66-5MHz-QPSK-132322-1-0-Low-5000-12000--56.67-PASS



Band66-5MHz-QPSK-132322-1-0-Low-12000-26500--41.75-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-QPSK-132647-1-0-High-30-1000--34.28-PASS



Band66-5MHz-QPSK-132647-1-0-High-1000-5000--40.91-PASS



Band66-5MHz-QPSK-132647-1-0-High-5000-12000--56.67-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-QPSK-132647-1-0-High-12000-26500--41.48-PASS



Band66-5MHz-16QAM-131997-1-0-Low-30-1000--34.66-PASS



Band66-5MHz-16QAM-131997-1-0-Low-1000-5000--39.25-PASS




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Band66-5MHz-16QAM-131997-1-0-Low-5000-12000--56.78-PASS



Band66-5MHz-16QAM-131997-1-0-Low-12000-26500--41.61-PASS



Band66-5MHz-16QAM-132322-1-0-Low-30-1000--34.88-PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity