

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.231 Certification
2BPQ2-PGRMSB2
25-0109
June 9, 2025
PBM Industries, Inc.
PGRM-SB2

INTERNAL PHOTOS




Figure 1. Front View cover removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.231 Certification
2BPQ2-PGRMSB2
25-0109
June 9, 2025
PBM Industries, Inc.
PGRM-SB2




Figure 2. Top of PCBA

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.231 Certification
2BPQ2-PGRMSB2
25-0109
June 9, 2025
PBM Industries, Inc.
PGRM-SB2




Figure 3. PCBA Bottom

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15.231 Certification
2BPQ2-PGRMSB2
25-0109
June 9, 2025
PBM Industries, Inc.
PGRM-SB2




Figure 4. Antenna details




Figure 5. Antenna location and placement