

1 STATEMENT

The label is affixed on an immovable part of the bottom side of the device.

There is no space to bear Part 15.19 statement due to the device is approximately a palm size, the font will unclear, which would impact revenue, the statement is specified in user manual.

2 LABEL LOCATION

