






Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz






EUT Mode


802.11be EHT80 Puncture 20RU1

Plot on Channel 6385 MHz




04:30:34 PM 02/02/2024

Plot on Channel 6785 MHz




05:10:51 PM 02/02/2024

Plot on Channel 6865 MHz



05:16:25 PM 02/02/2024

Plot on Channel 7025 MHz



05:38:39 PM 02/02/2024




EUT Mode

802.11be EHT80 Puncture 20RU2

Plot on Channel 6225 MHz

Plot on Channel 6705 MHz




EUT Mode

802.11be EHT80 Puncture 20RU4

Plot on Channel 6225 MHz

Plot on Channel 6705 MHz






EUT Mode


802.11be EHT80 Puncture 20RU8

Plot on Channel 5985 MHz




03:53:40 PM 02/02/2024

Plot on Channel 6465 MHz




04:36:53 PM 02/02/2024

Plot on Channel 6545 MHz



04:43:44 PM 02/02/2024


Plot on Channel 6625 MHz



04:48:35 PM 02/02/2024




Plot on Channel 6945 MHz






EUT Mode : 802.11be EHT160 Full RU


Plot on Channel 6025 MHz




Plot on Channel 6185 MHz



Plot on Channel 6345 MHz




Plot on Channel 6505 MHz







Plot on Channel 6665 MHz



Plot on Channel 6825 MHz



Plot on Channel 6985 MHz







EUT Mode


802.11be EHT160 Puncture 20RU128

Plot on Channel 6025 MHz

Plot on Channel 6665 MHz



Plot on Channel 6825 MHz






EUT Mode

802.11be EHT160 Puncture 20RU16

Plot on Channel 6185 MHz






EUT Mode


802.11be EHT160 Puncture 20RU1

Plot on Channel 6345 MHz

Plot on Channel 6505 MHz




10:18:01 AM 02/04/2024



10:26:37 AM 02/04/2024

Plot on Channel 6985 MHz



10:57:37 AM 02/04/2024





EUT Mode


802.11be EHT160 Puncture 40RU192

Plot on Channel 6025 MHz

Plot on Channel 6665 MHz



Plot on Channel 6825 MHz







EUT Mode


802.11be EHT160 Puncture 40RU3

Plot on Channel 6345 MHz

Plot on Channel 6505 MHz



Plot on Channel 6985 MHz






EUT Mode

802.11be EHT160 Puncture 40RU48

Plot on Channel 6185 MHz







MIMO <Ant. 3+4(4)>

EUT Mode : 802.11a


Plot on Channel 5955 MHz




Plot on Channel 6195 MHz



Plot on Channel 6415 MHz




Plot on Channel 6435 MHz






Plot on Channel 6475 MHz




11:45:26 AM 01/26/2024

Plot on Channel 6515 MHz




11:49:42 AM 01/26/2024

Plot on Channel 6535 MHz



11:54:49 AM 01/26/2024


Plot on Channel 6695 MHz




11:58:20 AM 01/26/2024




Plot on Channel 6855 MHz




Plot on Channel 6875 MHz




Plot on Channel 6895 MHz



Plot on Channel 6995 MHz




Plot on Channel 7095 MHz






EUT Mode : 802.11be EHT20 Full RU


Plot on Channel 5955 MHz



Plot on Channel 6195 MHz



Plot on Channel 6415 MHz



Plot on Channel 6435 MHz

