



CDD Mode


In-Band Emissions (Channel Mask)

MIMO <Ant. 3+4(3)>

EUT Mode


802.11a

Plot on 5955 MHz




05:45:26 PM 02/21/2025

Plot on 6195 MHz




06:01:50 PM 02/21/2025

Plot on 6415 MHz



06:20:01 PM 02/21/2025

Plot on 6435 MHz




06:32:41 PM 02/21/2025



FCC RADIO TEST REPORT


Report No. : FR4N0918G

Plot on 6475 MHz




06:42:52 PM 02/21/2025

Plot on 6515 MHz




06:59:08 PM 02/21/2025

Plot on 6535 MHz




07:13:01 PM 02/21/2025

Plot on 6695 MHz




07:22:45 PM 02/21/2025

Plot on 6855 MHz



07:30:44 PM 02/21/2025

Plot on 6875 MHz



07:57:44 PM 02/21/2025


TEL: 886-3-327-0868

FAX: 886-3-327-0855


Page Number : A2-2 10 of 95




Plot on 6895 MHz



Plot on 6995 MHz



Plot on 7095 MHz






MIMO <Ant. 3+4(4)>

EUT Mode


802.11a

Plot on 5955 MHz




06:16:42 PM 02/21/2025

Plot on 6195 MHz




06:33:06 PM 02/21/2025

Plot on 6415 MHz



06:51:18 PM 02/21/2025

Plot on 6435 MHz




07:03:57 PM 02/21/2025




FCC RADIO TEST REPORT

Report No. : FR4N0918G


Plot on 6475 MHz




Plot on 6515 MHz




Plot on 6535 MHz




Plot on 6695 MHz



Plot on 6855 MHz



Plot on 6875 MHz




TEL: 886-3-327-0868

FAX: 886-3-327-0855


Page Number : A2-2 13 of 95




Plot on 6895 MHz



Plot on 6995 MHz



Plot on 7095 MHz






MIMO <Ant. 3+4(3)>

EUT Mode


802.11be EHT20 FullRU

Plot on 5955 MHz




09:13:58 PM 02/21/2025

Plot on 6195 MHz




09:35:57 PM 02/21/2025

Plot on 6415 MHz



09:56:04 PM 02/21/2025


Plot on 6435 MHz




10:15:36 PM 02/21/2025




Plot on 6475 MHz




Plot on 6515 MHz




Plot on 6535 MHz




Plot on 6695 MHz



Plot on 6855 MHz




Plot on 6875 MHz







Plot on 6895 MHz



Plot on 6995 MHz



Plot on 7095 MHz






EUT Mode


802.11be EHT20 26RU0

Plot on 5955 MHz




05:37:58 PM 02/27/2025

Plot on 6435 MHz




08:22:41 PM 02/27/2025

Plot on 6535 MHz



10:29:02 PM 02/27/2025

Plot on 6895 MHz




01:33:11 AM 02/28/2025



EUT Mode


802.11be EHT20 26RU4

Plot on 6195 MHz




06:33:14 PM 02/27/2025

Plot on 6475 MHz




08:59:07 PM 02/27/2025

Plot on 6695 MHz



11:10:23 PM 02/27/2025

Plot on 6995 MHz




02:27:09 PM 02/28/2025



EUT Mode


802.11be EHT20 26RU8

Plot on 6415 MHz




07:24:05 PM 02/27/2025

Plot on 6515 MHz




09:42:27 PM 02/27/2025

Plot on 6855 MHz



12:01:22 AM 02/28/2025


Plot on 6875 MHz



12:49:00 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52RU37

Plot on 5955 MHz




05:43:11 PM 02/27/2025

Plot on 6435 MHz




08:26:31 PM 02/27/2025

Plot on 6535 MHz



10:32:55 PM 02/27/2025

Plot on 6895 MHz




01:42:13 PM 02/28/2025



EUT Mode


802.11be EHT20 52RU38

Plot on 6195 MHz




06:37:04 PM 02/27/2025

Plot on 6475 MHz




09:05:09 PM 02/27/2025

Plot on 6695 MHz



11:20:53 PM 02/27/2025

Plot on 6995 MHz




02:31:07 AM 02/28/2025



EUT Mode


802.11be EHT20 52RU40

Plot on 6415 MHz




07:34:27 PM 02/27/2025

Plot on 6515 MHz




09:49:35 PM 02/27/2025

Plot on 6855 MHz



12:08:34 AM 02/28/2025


Plot on 6875 MHz



12:52:54 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52T+26T70

Plot on 5955 MHz




06:10:00 PM 02/27/2025

Plot on 6435 MHz




08:45:07 PM 02/27/2025

Plot on 6535 MHz



10:51:38 PM 02/27/2025

Plot on 6895 MHz




02:08:07 AM 02/28/2025



EUT Mode


802.11be EHT20 52T+26T71

Plot on 6195 MHz




01:02:19 PM 02/27/2025

Plot on 6475 MHz




09:23:48 PM 02/27/2025

Plot on 6695 MHz



11:39:40 PM 02/27/2025

Plot on 6995 MHz




02:59:02 AM 02/28/2025



EUT Mode


802.11be EHT20 52T+26T72

Plot on 6415 MHz




07:59:45 PM 02/27/2025

Plot on 6515 MHz




10:08:18 PM 02/27/2025

Plot on 6855 MHz



12:26:12 AM 02/28/2025


Plot on 6875 MHz



01:17:05 AM 02/28/2025



Plot on 7095 MHz




03:59:33 AM 02/28/2025



EUT Mode


802.11be EHT20 106RU53

Plot on 5955 MHz




05:59:24 PM 02/27/2025

Plot on 6195 MHz




06:51:58 PM 02/27/2025

Plot on 6435 MHz



08:36:54 PM 02/27/2025


Plot on 6475 MHz



09:13:22 PM 02/27/2025




Plot on 6535 MHz




10:41:11 PM 02/27/2025

Plot on 6695 MHz




11:24:47 PM 02/27/2025

Plot on 6895 MHz



01:57:29 AM 02/28/2025

Plot on 6995 MHz




02:46:20 AM 02/28/2025



EUT Mode


802.11be EHT20 106RU54

Plot on 6415 MHz




01:49:22 PM 02/27/2025

Plot on 6515 MHz




09:57:51 PM 02/27/2025

Plot on 6855 MHz



12:14:41 AM 02/28/2025


Plot on 6875 MHz



01:06:40 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 106T+26T82

Plot on 5955 MHz




06:28:09 PM 02/27/2025

Plot on 6435 MHz




08:53:05 PM 02/27/2025

Plot on 6535 MHz



11:02:06 PM 02/27/2025

Plot on 6895 MHz




02:23:12 AM 02/28/2025



EUT Mode


802.11be EHT20 106T+26T83

Plot on 6195 MHz




01:18:05 PM 02/27/2025

Plot on 6415 MHz




08:15:34 PM 02/27/2025

Plot on 6475 MHz



09:38:35 PM 02/27/2025

Plot on 6515 MHz




10:22:58 PM 02/27/2025



FCC RADIO TEST REPORT


Report No. : FR4N0918G

Plot on 6695 MHz




11:50:52 PM 02/27/2025

Plot on 6855 MHz




12:41:47 AM 02/28/2025

Plot on 6875 MHz




01:27:03 AM 02/28/2025

Plot on 6995 MHz



03:13:06 AM 02/28/2025

Plot on 7095 MHz



04:15:58 AM 02/28/2025

TEL: 886-3-327-0868

FAX: 886-3-327-0855

Page Number : A2-2 36 of 95




MIMO <Ant. 3+4(4)>

EUT Mode


802.11be EHT20 FullRU

Plot on 5955 MHz




09:45:14 PM 02/21/2025

Plot on 6195 MHz




10:07:13 PM 02/21/2025

Plot on 6415 MHz



10:27:20 PM 02/21/2025

Plot on 6435 MHz




10:46:52 PM 02/21/2025



FCC RADIO TEST REPORT


Report No. : FR4N0918G

Plot on 6475 MHz




11:07:22 PM 02/21/2025

Plot on 6515 MHz




11:26:56 PM 02/21/2025

Plot on 6535 MHz




11:46:38 PM 02/21/2025

Plot on 6695 MHz




12:06:21 AM 02/22/2025

Plot on 6855 MHz



12:27:39 AM 02/22/2025

Plot on 6875 MHz



08:19:04 PM 02/25/2025


TEL: 886-3-327-0868

FAX: 886-3-327-0855


Page Number : A2-2 38 of 95




Plot on 6895 MHz



Plot on 6995 MHz



Plot on 7095 MHz






EUT Mode


802.11be EHT20 26RU0

Plot on 5955 MHz




06:09:30 PM 02/27/2025

Plot on 6435 MHz




08:54:13 PM 02/27/2025

Plot on 6535 MHz



11:00:34 PM 02/27/2025

Plot on 6895 MHz




02:04:43 AM 02/28/2025



EUT Mode


802.11be EHT20 26RU4

Plot on 6195 MHz




07:04:46 PM 02/27/2025

Plot on 6475 MHz




09:30:39 PM 02/27/2025

Plot on 6695 MHz



11:41:56 PM 02/27/2025

Plot on 6995 MHz




02:58:42 AM 02/28/2025



EUT Mode


802.11be EHT20 26RU8

Plot on 6415 MHz




01:55:38 PM 02/27/2025

Plot on 6515 MHz




10:13:59 PM 02/27/2025

Plot on 6855 MHz



12:32:54 AM 02/28/2025


Plot on 6875 MHz



01:20:32 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52RU37

Plot on 5955 MHz




06:14:43 PM 02/27/2025

Plot on 6435 MHz




08:58:04 PM 02/27/2025

Plot on 6535 MHz



11:04:27 PM 02/27/2025

Plot on 6895 MHz




02:13:45 AM 02/28/2025



EUT Mode


802.11be EHT20 52RU38

Plot on 6195 MHz




01:08:36 PM 02/27/2025

Plot on 6475 MHz




09:36:41 PM 02/27/2025

Plot on 6695 MHz



11:52:25 PM 02/27/2025

Plot on 6995 MHz




03:02:39 AM 02/28/2025



EUT Mode


802.11be EHT20 52RU40

Plot on 6415 MHz




08:05:59 PM 02/27/2025

Plot on 6515 MHz




10:21:07 PM 02/27/2025

Plot on 6855 MHz



12:40:04 AM 02/28/2025


Plot on 6875 MHz



01:24:26 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 52T+26T70

Plot on 5955 MHz




06:41:33 PM 02/27/2025

Plot on 6435 MHz




09:16:39 PM 02/27/2025

Plot on 6535 MHz



11:23:10 PM 02/27/2025

Plot on 6895 MHz



02:39:39 PM 02/28/2025