




EUT Mode


802.11be EHT20 52T+26T71

Plot on 6195 MHz




01:33:51 PM 02/27/2025

Plot on 6475 MHz




09:55:19 PM 02/27/2025

Plot on 6695 MHz



12:11:12 AM 02/28/2025

Plot on 6995 MHz




03:30:34 AM 02/28/2025



EUT Mode


802.11be EHT20 52T+26T72

Plot on 6415 MHz




08:31:17 PM 02/27/2025

Plot on 6515 MHz




10:39:50 PM 02/27/2025

Plot on 6855 MHz



12:57:44 AM 02/28/2025


Plot on 6875 MHz



01:48:37 AM 02/28/2025



Plot on 7095 MHz




04:31:05 AM 02/28/2025



EUT Mode


802.11be EHT20 106RU53

Plot on 5955 MHz




06:30:56 PM 02/27/2025

Plot on 6195 MHz




07:23:30 PM 02/27/2025

Plot on 6435 MHz



09:08:26 PM 02/27/2025


Plot on 6475 MHz



09:44:54 PM 02/27/2025




Plot on 6535 MHz




11:12:43 PM 02/27/2025

Plot on 6695 MHz




11:56:19 PM 02/27/2025

Plot on 6895 MHz



02:29:02 AM 02/28/2025

Plot on 6995 MHz




03:17:52 AM 02/28/2025



EUT Mode


802.11be EHT20 106RU54

Plot on 6415 MHz




08:20:54 PM 02/27/2025

Plot on 6515 MHz




10:29:23 PM 02/27/2025

Plot on 6855 MHz



12:46:13 AM 02/28/2025


Plot on 6875 MHz



01:38:12 AM 02/28/2025



Plot on 7095 MHz






EUT Mode


802.11be EHT20 106T+26T82

Plot on 5955 MHz




06:59:41 PM 02/27/2025

Plot on 6435 MHz




09:24:37 PM 02/27/2025

Plot on 6535 MHz



11:33:39 PM 02/27/2025

Plot on 6895 MHz




02:54:44 AM 02/28/2025



EUT Mode


802.11be EHT20 106T+26T83

Plot on 6195 MHz




01:49:37 PM 02/27/2025

Plot on 6415 MHz




08:47:06 PM 02/27/2025

Plot on 6475 MHz



10:10:07 PM 02/27/2025

Plot on 6515 MHz




10:54:31 PM 02/27/2025




FCC RADIO TEST REPORT

Report No. : FR4N0918G


Plot on 6695 MHz




Plot on 6855 MHz




Plot on 6875 MHz



Plot on 6995 MHz



Plot on 7095 MHz






MIMO <Ant. 3+4(3)>

EUT Mode


802.11be EHT40 FullIRU

Plot on 5965 MHz




11:07:23 PM 02/25/2025

Plot on 6205 MHz




11:22:35 PM 02/25/2025

Plot on 6405 MHz



11:36:10 PM 02/25/2025

Plot on 6445 MHz




11:52:13 PM 02/25/2025



FCC RADIO TEST REPORT


Report No. : FR4N0918G

Plot on 6485 MHz




12:08:42 AM 02/26/2025

Plot on 6525 MHz




12:24:31 AM 02/26/2025

Plot on 6565 MHz




12:37:25 AM 02/26/2025

Plot on 6685 MHz




12:52:32 AM 02/26/2025

Plot on 6845 MHz



01:08:29 AM 02/26/2025

Plot on 6885 MHz



01:25:21 AM 02/26/2025


TEL: 886-3-327-0868

FAX: 886-3-327-0855


Page Number : A2-2 60 of 95




Plot on 6925 MHz



Plot on 7005 MHz



Plot on 7085 MHz






MIMO <Ant. 3+4(4)>

EUT Mode


802.11be EHT40 FullRU

Plot on 5965 MHz




11:38:56 PM 02/25/2025

Plot on 6205 MHz




11:54:07 PM 02/25/2025

Plot on 6405 MHz



12:07:42 AM 02/26/2025


Plot on 6445 MHz



12:23:46 AM 02/26/2025




Plot on 6485 MHz




12:40:15 AM 02/26/2025

Plot on 6525 MHz




12:56:04 AM 02/26/2025

Plot on 6565 MHz




01:08:58 AM 02/26/2025

Plot on 6685 MHz




01:24:04 AM 02/26/2025

Plot on 6845 MHz



01:40:01 AM 02/26/2025


Plot on 6885 MHz




01:56:53 AM 02/26/2025




Plot on 6925 MHz



Plot on 7005 MHz



Plot on 7085 MHz






MIMO <Ant. 3+4(3)>

EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




02:16:13 AM 02/26/2025

Plot on 6225 MHz




02:23:30 AM 02/26/2025

Plot on 6385 MHz



02:31:01 AM 02/26/2025

Plot on 6465 MHz




02:40:26 AM 02/26/2025




FCC RADIO TEST REPORT

Report No. : FR4N0918G


Plot on 6545 MHz




Plot on 6625 MHz




Plot on 6705 MHz




Plot on 6785 MHz



Plot on 6865 MHz



Plot on 6945 MHz




TEL: 886-3-327-0868

FAX: 886-3-327-0855

Page Number : A2-2 66 of 95



Plot on 7025 MHz




03:49:17 AM 02/26/2025



EUT Mode


802.11be EHT80 Puncture20 1

Plot on 6385 MHz




05:13:09 AM 02/28/2025

Plot on 6785 MHz




06:55:53 AM 02/28/2025

Plot on 6865 MHz



07:17:59 AM 02/28/2025


Plot on 7025 MHz



07:38:49 AM 02/28/2025


**EUT Mode** 802.11be EHT80 Puncture20 2

Plot on 6225 MHz



04:43:33 AM 02/28/2025


Plot on 6705 MHz



06:14:29 AM 02/28/2025


EUT Mode 802.11be EHT80 Puncture20 4

Plot on 6225 MHz



04:59:16 AM 02/28/2025

Plot on 6705 MHz




06:34:41 AM 02/28/2025



EUT Mode


802.11be EHT80 Puncture20 8

Plot on 5985 MHz




04:27:23 AM 02/28/2025

Plot on 6465 MHz




05:25:31 AM 02/28/2025

Plot on 6545 MHz



05:39:23 AM 02/28/2025


Plot on 6625 MHz



05:54:11 AM 02/28/2025



Plot on 6945 MHz



07:26:26 AM 02/28/2025




MIMO <Ant. 3+4(4)>

EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




02:47:45 AM 02/26/2025

Plot on 6225 MHz




02:55:02 AM 02/26/2025

Plot on 6385 MHz



03:02:34 AM 02/26/2025

Plot on 6465 MHz




03:11:59 AM 02/26/2025




FCC RADIO TEST REPORT

Report No. : FR4N0918G


Plot on 6545 MHz




Plot on 6625 MHz




Plot on 6705 MHz




Plot on 6785 MHz



Plot on 6865 MHz



Plot on 6945 MHz




TEL: 886-3-327-0868

FAX: 886-3-327-0855

Page Number : A2-2 73 of 95



Plot on 7025 MHz







EUT Mode

802.11be EHT80 Puncture20 1


Plot on 6385 MHz




Plot on 6785 MHz



Plot on 6865 MHz




Plot on 7025 MHz






EUT Mode	802.11be EHT80 Puncture20 2
----------	-----------------------------

Plot on 6225 MHz



05:15:06 AM 02/28/2025

Plot on 6705 MHz




06:46:01 AM 02/28/2025



EUT Mode


802.11be EHT80 Puncture20 4

Plot on 6225 MHz



05:30:48 AM 02/28/2025

Plot on 6705 MHz




07:06:13 AM 02/28/2025




EUT Mode 802.11be EHT80 Puncture20 8

Plot on 5985 MHz




04:58:55 AM 02/28/2025

Plot on 6465 MHz




05:57:03 AM 02/28/2025

Plot on 6545 MHz



06:09:55 AM 02/28/2025


Plot on 6625 MHz



06:25:43 AM 02/28/2025



Plot on 6945 MHz



01:57:57 AM 02/28/2025




MIMO <Ant. 3+4(3)>

EUT Mode


802.11be EHT160 FullRU

Plot on 6025 MHz




03:52:39 AM 02/26/2025

Plot on 6185 MHz




03:56:01 AM 02/26/2025

Plot on 6345 MHz



03:59:44 AM 02/26/2025


Plot on 6505 MHz




04:24:06 AM 03/27/2025




Plot on 6665 MHz



Plot on 6825 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6345 MHz




08:13:39 AM 02/28/2025

Plot on 6505 MHz



04:24:59 AM 03/27/2025

Plot on 6985 MHz




04:27:42 AM 03/27/2025



EUT Mode	802.11be EHT160 Puncture20 16
----------	-------------------------------

Plot on 6185 MHz




07:54:20 AM 02/28/2025



EUT Mode


802.11be EHT160 Puncture20 128

Plot on 6025 MHz




07:41:06 AM 02/28/2025

Plot on 6665 MHz



08:35:32 AM 02/28/2025

Plot on 6825 MHz




08:44:32 AM 02/28/2025




EUT Mode 802.11be EHT160 Puncture40 3


Plot on 6345 MHz



Plot on 6505 MHz




Plot on 6985 MHz





EUT Mode	802.11be EHT160 Puncture40 48
----------	-------------------------------

Plot on 6185 MHz




08:06:19 AM 02/28/2025




EUT Mode

802.11be EHT160 Puncture40 192


Plot on 6025 MHz



Plot on 6665 MHz



Plot on 6825 MHz






MIMO <Ant. 3+4(4)>

EUT Mode


802.11be EHT160 FullIRU

Plot on 6025 MHz




04:24:12 AM 02/26/2025

Plot on 6185 MHz




04:27:33 AM 02/26/2025

Plot on 6345 MHz



04:31:17 AM 02/26/2025


Plot on 6505 MHz




10:14:46 AM 03/27/2025




Plot on 6665 MHz



Plot on 6825 MHz




Plot on 6985 MHz






EUT Mode 802.11be EHT160 Puncture20 1


Plot on 6345 MHz



Plot on 6505 MHz



Plot on 6985 MHz






EUT Mode

802.11be EHT160 Puncture20 16

Plot on 6185 MHz




08:25:52 AM 02/28/2025




EUT Mode 802.11be EHT160 Puncture20 128


Plot on 6025 MHz



Plot on 6665 MHz



Plot on 6825 MHz






EUT Mode


802.11be EHT160 Puncture40 3

Plot on 6345 MHz




08:52:00 AM 02/28/2025

Plot on 6505 MHz



10:16:33 AM 03/27/2025

Plot on 6985 MHz




10:19:16 AM 03/27/2025



EUT Mode 802.11be EHT160 Puncture40 48

Plot on 6185 MHz




08:37:50 AM 02/28/2025




EUT Mode	802.11be EHT160 Puncture40 192
----------	--------------------------------

Plot on 6025 MHz



Plot on 6665 MHz



Plot on 6825 MHz

