

**INTERTEK TESTING SERVICE**

---

Report No: HK09060258-2

**Configuration Photographs**

**Worst-Case Radiated Emissions**

**(Front View)**

**Model : 40-268**



# INTERTEK TESTING SERVICE

---

Report No: HK09060258-2

## Configuration Photographs Worst-Case Radiated Emissions

(Back View)

Model : 40-268

