


Photographs of the Device

Internal Front View – Transceiver Module




Photographs of the Device

Internal Front View – Transceiver Module Circuit Board Top View




Photographs of the Device

Internal Front View – Transceiver Module, Control Section




Photographs of the Device

Internal Front View – Transceiver Module, Exciter Section




Photographs of the Device

Internal Front View – Transceiver Module, Receiver Section



Photographs of the Device

Internal Front View – Power Amplifier Module, Cover Removed




Photographs of the Device

Internal Front View – Power Supply Module



Photographs of the Device

Internal Front View – Power Supply Module, Circuit Boards, Top View




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC3790


Photographs of the Device

Internal Front View – Backplane



Photographs of the Device

Internal Back View – Transceiver Module



Photographs of the Device

Internal Back View – Power Amplifier Module



Photographs of the Device

Internal Back View – Power Supply Module, Circuit Boards, Back View



APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC3790

Photographs of the Device

Internal Back View – Backplane




EXHIBIT C4-4