

Appendix D. SAR Test Setup Photos



Bottom Face, Test Separation 0 mm



Bottom Face with Scanner+Battery 2,
Test Separation 0 mm



Bottom Face with USB+Battery 2,
Test Separation 0 mm



Edge1, Test Separation 0 mm




**Edge1 with Scanner+Battery 2,
Test Separation 0 mm**



**Edge1 with USB+Battery 2,
Test Separation 0 mm**



Edge4, Test Separation 0 mm



**Edge4 with Scanner+Battery 2,
Test Separation 0 mm**



**Edge4 with USB+Battery 2,
Test Separation 0 mm**