


Date of issue: 26 February 2021

Photographs of the ANTENNA UNIT RSB-144-129 for MARINE RADAR FAR-2268DS 1 Internal view


1.1 Right side view (with the side cover removed, showing MTR-DRV board 03P9560, RF-TB board 03P9712 and MIC board 03P9569)





Date of issue: 26 February 2021


1.2 MTR-DRV board module





Date of issue: 26 February 2021


1.3 MTR-DRV board module (with removed from metal base parts)





Date of issue: 26 February 2021


1.4 RF-TB board module





Date of issue: 26 February 2021


1.5 RF-TB board module (with removed from the metal base part)






Date of issue: 26 February 2021

1.6 Right side view (with MTR-DRV board 03P9560 and RF-TB board 03P9712 removed, showing RFC board 03P9540 and MIC board 03P9569)






1.7 RFC board module






1.8 RFC board module (with removed from the metal base part)






Date of issue: 26 February 2021

1.9 MIC board module





1.10 MIC board module (with the metallic cover opened)





Date of issue: 26 February 2021


1.11 Right side view (with RFC board 03P9540 and MIC board 03P9569 removed, showing IF board 03P9666 and IF-TB board 03P9711 module)





Date of issue: 26 February 2021


1.12 IF board 03P9666 and IF-TB board 03P9711 module (with the metallic cover removed, showing IF board 03P9666)





Date of issue: 26 February 2021


1.13 IF board 03P9666 and IF-TB board 03P9711 module (with IF board 03P9666 removed from the metallic case, showing IF-TB board 03P9711)





Date of issue: 26 February 2021

1.14 Right side view (with IF board 03P9666 and IF-TB board 03P9711 module, and the metallic base part removed, showing the fan)





1.15 Right side view (with the fan and metallic base part removed)





Date of issue: 26 February 2021

1.16 Left side view (with the left side cover removed, showing Transceiver RTR-129)





1.17 Left side view (with the cover removed and showing the magnetron)






1.18 Right side view (with Transceiver RTR-129 and the magnetron removed)





1.19 Transceiver RTR-129, Front side (showing BUF board 03P9446)






1.20 Transceiver RTR-129, Front side (with BUF board 03P9446 removed)






1.21 Transceiver RTR-129, Rear side





Date of issue: 26 February 2021


1.22 Transceiver RTR-129, Rear side (with the metallic cover removed, showing PFN1 board 03P9431, PFN2 board 03P9445 and PFN3 board 03P9433)





Date of issue: 26 February 2021


1.23 Transceiver RTR-129, Rear side (with PFN1 board 03P9431, PFN2 board 03P9445 removed, showing RELAY board 03P9693, SCR1 / SCR2 / SCR3 boards 03P9549 and PFN3 board 03P9433)





Date of issue: 26 February 2021

1.24 Transceiver RTR-129, Rear side (with RELAY board 03P9693, SCR1 / SCR2 / SCR3 boards 03P9549 and PFN3 board 03P9433 removed)



End of text