



**Ultratech's  
Accreditations:**



0685



C-1376



3000 Bristol Circle,  
Oakville, Ontario,  
Canada L6H 6G4

Tel.: (905) 829-1570  
Fax.: (905) 829-8050

Website: [www.ultratech-labs.com](http://www.ultratech-labs.com)  
Email: [vic@ultratech-labs.com](mailto:vic@ultratech-labs.com)

September 19, 2007

**AmericanTCB, Inc.**  
6731 Whittier Avenue, Suite C110  
McLean, VA 22101

**Subject: Class II Permissive Change Certification in accordance with FCC 47 CFR Parts 2 and 90 (Subpart I) - Non-Broadcast Radio Transceivers Operating in the frequency bands 400-430 MHz (12.5 kHz and 25 kHz Channel Spacing).**

**Product: UHF FM REPEATER**  
**Model: IC-FR4000-1**  
**FCC ID: AFJ236801**

Dear Sir/Madam:

As appointed agent for **ICOM Incorporated**, we submit the application to AmericanTCB, Inc. for certification of the above product. Please review all files uploaded to ATCB electronic filing site.

Class II Permissive Change Description:

The 2SC72SC3012 (Q2) and SC-1322 (IC1) on the P50 PA unit is out of production. A new PA board with new power module IC, RA60H4047M1 is created in place of the 50PA board and VARISTOR board.

Update Summary

Board name	Update info.	Reason of update
50PA	Delete	Q2 and IC1 on 50PA board is out of production
VARISTOR	Delete	This board is deleted, and combined the circuit to new 50PA-MOS board
50PA-MOS	Add	Created new 50PA board with new substituted parts, IC1

If you have any queries, please do not hesitate to contact us by our TOLL FREE number:

OUR TELEPHONE NO.: 1-877-747-6381

Yours truly,



Tri Minh Luu, P.Eng  
Vice President - Engineering