



Icom Inc.  
1-1-32, Kamiminami, Hirano-ku, Osaka 547-0003 Japan.  
Phone : 06 6793 5302 Fax : 06 6793 0013  
e-mail: world\_support@icom.co.jp

Date: August 28, 2012

Federal Communications Commission  
Authorization & Evaluation Division  
7435 Oakland Mills Road  
Colombia, Maryland 21046

**To Whom It May Concern**

Subject: Class2 permissive change  
Model: IC-F4161T/S/DT/DS  
FCC ID : AFJ289401

Dear Sir/Madam,

This is to inform you that there is class 2 permissive change on IC-F4161T/S/DT/DS to change its feature.

The contents of this change are a final AMP and some parts.

Please find attached the "difference of parts" about hardware update for details.

Thank you for your attention to this matter.

Icom Incorporated

Hideji Fujishima  
General Manager of Quality Department

IC-F4161D Difference Parts List

RF Unit

REF No.	OLD	NEW
Q601	RD07MVS2-T112 *	RD07MUS2B-T112
L610	-	ELJRE 1N5ZFA 1.5N
R619	ERJ3GE-JPW	-
R621	39K ERJ2GE	22K ERJ2GE
C620	4P C1608 CH B	2P C1608 CH B
C622	-	4P C1608 CH B
C624	39P GQM18 CH	30P C1608 CH
C635	0.001 C1005 B	47P C1005 CH
C636	0.01 C1005 25V B	1 C1005 10V B
C643	22P C1005 CH	-
C667	47P C1005 CH	0.001 C1005 B