

Dward ATCB

From: webrobot@americantcb.com
Sent: 05/18/2006 6:25 AM
To: dward@americantcb.com
Cc: whgraff@americantcb.com; murban@americantcb.com; marianne@americantcb.com
Subject: MESSAGE/uelrfiatcb/AFJ289401_ATCB003473

From: Mr. Tri Luu (uelrfiatcb) <mailto:tri@ultratech-labs.com>

Hello Dennis,

1. Please note that each application must stand on its own. Consequently, while you verified auto bandwidth data in the last app, it still needs to be verified in this app. Please either provide a cover page stating Occupied BW measurements are done in auto mode on the analyzer or please provide a corrected report showing auto function for BW in the report.

A1) Please see the revised cover letter uploaded to ATCB web site.

2. Please note that it does not appear from the SAR plots that the location and orientation of the EUT have been clearly identified. Please provide a SAR report with the EUT superimposed on the data plots.

A2) Please see the revised SAR test report uploaded to ATCB web site.

Regards,
JaeWook Choi
UltraTech Labs.