
APPENDIX 3: Photographs of test setup

Radiated Spurious Emission

Front



Rear (below 30 MHz, Horizontal)



Rear (below 30 MHz, Vertical)



Rear (below 1 MHz)



Rear (above 1 GHz)



UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Worst Case Position

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401