

MX-1000 /DocuPrint P8 BLOCK DIAGRAM

- (note)
 *APC: Auto Power Control
 *BD: Beam Detector
 *PS: Power Supply
 *ICU: I/F Control Unit
 *PE: Paper Empty Sensor
 *Pin: Paper In Sensor
 *Pout: Paper Out Sensor

