

FAX

AIRTRONICS, INC.

1185 STANFORD CT. ANAHEIM, CA. 92805

Phone: (714) 978 1895

Fax: (714) 978 1540

Federal Communications Commission

TO : Equipment Authorization Division

FAX NO : (301) 344 2050

ATTN: Joe Dichoso

PAGES : /

FROM: John Elliot, JR.

DATE : 8, February, '99

Ref: FCC ID AXYTX029, YOUR REF # 5946 AND # 4901

1. ref item #1. Users/instruction manual submitted 14 December, '98 per your reference number 4901. Our Code of Federal Regulations manual (dated 1 October, 1995) does not list "Section 95.653."
2. ref item #2. Section 95.207 (a)2, use of device for remote control of model aircraft is defined on page 6 of users manual.
3. ref item #3. Section 95.647 mentions "Crystal control required." Reference to "Antenna gain" and if "antenna is integral (non-removable)." The antenna is a $\frac{1}{4}$ wave whip with zero gain and is an integral part of the RD6000 transmitter.
4. ref item #4. Section 95.645 Re-identified as Section 95.641 "Control accessibility" in Federal Regulations manual dated 1 October, 1995. Transmitter has no controls, switches, or adjustments that are accessible from the control panel, that when manipulated, would result in any violation of the rules.

Section 95.649. A supplemental instruction sheet is included with the manual that defines proper and safe installation of airborne components and range checking; the manual details proper operation of the transmitter with respect to normal flight control adjustments. Should service be required, the customer is requested to return the system or components for service.

A current copy of the operating manual, Publishers changes to RD6000 manual, and the supplemental instruction sheet is included for your approval.

Thank you for your assistance today in interpreting Section Number difference's between the '95 and '97 regulations!

Sincerely,

John Elliot, Jr.
Customer Relations Manager

TO BE FED EX'D
TODAY

FAX**AIRTRONICS, INC.**
1185 STANFORD CT. ANAHEIM, CA. 92805


Phone: (714) 978 1895

Fax: (714) 978 1540

Federal Communications Commission
TO : Equipment Authorization Division**FAX NO : (301) 362 3024****ATTN: Joe Dichoso****PAGES :****FROM: John Elliot, JR.****DATE : 5, February, '99****Ref: FCC ID AXYTX029, YOUR REF # 5946 AND # 4901**

1. ref item #1. Users/instruction manual submitted 14 December, '98 per your reference number 4901. Our Code of Federal Regulations manual (dated 1 October, 1995) does not list "Section 95.653."
2. ref item #2. Section 95.207 (a)2, use of device for remote control of model aircraft is defined on page 6 of users manual.
3. ref item #3. Section 95.647 mentions "Crystal control required." Reference to "Antenna gain" and if "antenna is integral (non-removable)." The antenna is a 1/4 wave whip with zero gain and is an integral part of the RD6000 transmitter.
4. ref item #4. Section 95.645 "Power capability." The transmitter has no provisions for increasing RF power output.
Section 96.649(?) Should "96.649" have read '95.649'?
We are shipping via FedEx this date one final copy of the operating manual complete with an insert of the "publishers changes to RD6000 manual" and a universal insert providing necessary safety and installation information.

Sincerely,


John Elliot, Jr.

Customer Relations Manager