



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

B.1. Radiated Measurement at Chamber

Frequency Below to 1GHz



Side



File Number: C1M1911123

Report Number: EM-F190483






New Taipei City244, Taiwan

Tel: +886 2 26099301 Fax: +886 2 26099303

Stand






AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

Frequency Above to 1GHz

Lie



Side







Tel: +886 2 26099301 Fax: +886 2 26099303

Stand





AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

B.2. RF Conducted Measurement

