



Date: 18th November 2002

Steve Dayhoff
Authorization & Evaluation Division
Federal Communications Commission Laboratory
7435 Oakland Mills Road
Columbia, MD 21046

Re: Form 731 Confirmation Number: EA149913 with FCC ID: AZ489FT5820.

Dear Mr. Dayhoff;

Motorola Inc., 8000 West Sunrise Boulevard, Fort Lauderdale, Florida 33322, herein submits its response to your 6th November 2002 request for information on FCC ID: AZ489FT5820, EA149913 via correspondence number 24287.

Q1) SAR rept pg 5 shows wrong FCC ID: ABZ99FT5820

R1) The FCC ID has been corrected in the attached revised report herein entitled "FCC rpt_R750Plus_021106_RevA.pdf".

Q2) User manual and SAR report antenna model numbers do not agree. Please confirm antenna options.

R2) The User Manual is corrected to reflect the correct antenna options. A revised User Manual is attached.

Q3) Please submit installation instructions for vehicle-mount antenna kit. What is ERP for vehicle mount antennas?

R3) Mobile antenna installation instructions attached. The maximum ERP of the mobile antenna is 1.73 Watt and the minimum ERP is 0.94 Watt. Measurements were done in Hermon laboratories, a FCC authorized test house.

Q4) User manual pg 68 refers to occupational SAR limits, while cover

R4) See the correction in the attached revised Users Manual.

Q5) Please clarify power units in SAR reports section 7.1.

R5) The power reference unit has been corrected in the attached revised report entitled "FCC rpt_R750Plus_021106_RevA.pdf".

If you have any questions with the above responses, please call me at 954-723-5793.

Sincerely,

/s/ Mike Ramnath

FCC Liaison

Email: mike.ramnath@motorola.com