

**EXHIBIT 7 ADDENDUM. Measurement Procedures and Test Equipment Used
Pursuant 47 CFR 2.947**

<u>SECTION</u>	<u>MEASUREMENT</u>	<u>ORIGINAL EXHIBIT</u>	<u>REFERENCE</u>
I.	Radiated Spurious Emissions	7C	2.974(e), 2.1053

I. Radiated Spurious Emissions – Pursuant 47 CFR 2.974(e), 2.1053

Following are photographs of the Radiated Spurious Emissions test setup.



PDR 3500 on table for scan. Dummy load connected to transmitter; antenna connected to receiver; PTT and Power cables running to connections under turntable.



Wide view of OATS setup. Antenna and mast to the left, PDR 3500 on table to the right.