



COREWILL CO.,LTD.

602, London Bldg, 1484-1, Sillim-dong, Gwanak-gu, Seoul, Korea

Tel. +82-2-863-0155

Fax +82-2-863-0154

ATTESTATION STATEMENT

In re : COREWILL CO.,LTD.

FCC ID: AZXHDK-2000

Date : March 20, 2012

15.247(a)(1)

The hopping sequence must be pseudorandom all Channels are used equally on average the receiver input bandwidth is approximately equal to the transmit bandwidth the receiver hops in sequence with the transmitted signal

15.247(g)

The system is designed to comply with all of the regulations in Section 15.247 when the transmitter is presented with a continuous data (or information)

15.247(h)

The system does not coordinate its channel selection/hopping sequence with other frequency hopping systems for the express purpose of avoiding the simultaneous occupancy of individual hopping frequencies by multiple transmitters.

Sincerely,

A handwritten signature in black ink, appearing to be "Hyoun-Soo, JANG", written over a horizontal line.

**Hyoun-Soo, JANG / General Manager
COREWILL CO.,LTD.**