



Date: June 23, 2022

**Federal Communications Commission
Authorization and Evaluation Division**

7435 Oakland Mills Rd
Columbia MD 21046-1609

Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

This application by HP Inc. will establish a new FCC ID under FCC ID: **B94HCL03WC** for the purpose of marketing.


The original grant to **ASAP Technology(Jiangxi) Co., Ltd.**, FCC ID: **2APXN-HSCL03WC** will remain in effect.

Per 2.933(b)

- (1) The original identification is FCC ID: **2APXN-HSCL03WC**
- (2) The original grant date is **08 Dec, 2021**
- (3) The equipment is electrically and functionally identical. Only the **FCC ID number** is different.
- (4) The hardware and software is identical with original granted.
- (5) The original test results are applicable and representative of this changed device.

Sincerely yours,

Applicant : HP Inc.
Address : 3390 East Harmony Road, Fort Collins, Colorado 80528, United States

Signature : 

Name and Job Title. : Frances.Liang, Manager
E-mail : frances.liang@hp.com
Tel. : 886 2-3789-2469