



810 Shimoimaizumi, Ebina-city,
Kanagawa 243-0460 Japan

Jul 14, 2011

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road Columbia,
MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: **BBP-PRSP34101**

Applicant: **Ricoh Company Ltd**

Dear Examiner,

This is to request a Class II Permissive change for FCC ID: BBP-PRSP34101 originally granted on 10/13/2009.

The change under this application is adding a Engine Board (Alternate).

The main differences between original Engine Board and alternate Engine Board are MCU and OSC.

- 1.MCU: HD64F2364VTE34V is changed to R4F24255NVFPU.
- 2.OSC: MA-406-24.576MHZ-10PF is changed to MA-406-12.288MHZ-16PF.
- 3.C36,C37,R76 around OSC are changed.

Sincerely,

Print Name: Taku Matsuyama
Title: Group Leader
Company Name: Ricoh Company Ltd