





(Front)




(Side)

Configuration of EUT and connecting equipments.
FAX reception operation mode(FAX mode)
(AC Powerline Conducted Emission)

Picture 1



(Front)



(Side)

Configuration of EUT and connecting equipments.


PC print operation mode(PC mode)

(AC Powerline Conducted Emission)

Picture 2



(Front)




(Rear)

Configuration of EUT and connecting equipments.
FAX reception operation mode(FAX mode)
(Radiated Emission)

Picture 3



(Front)



(Rear)

Configuration of EUT and connecting equipments.
PC print operation mode(PC mode)
(Radiated Emission)

Picture 4