





Main

Part Location







FV92A EAX61426201(8) 10.01.07 LUBREN



06E258041AA

0055284100



FMTX

Part Location


REMOTE SOLUTION CO.,LTD.

INSTITUTION: 2010.01.20	SPECIFICATION	MODEL NO:	7
REFORM : 2010.02.17		EBT60936201	13
DECISION : 2010.02.17			

HX300G-JE Control B/D

10. PCB LAYOUT


1) Top View



REMOTE SOLUTION CO.,LTD.

INSTITUTION: 2010.01.20	SPECIFICATION HX300G-JE Control B/D	MODEL NO:	7
REFORM : 2010.02.17		EBT60936201	13
DECISION : 2010.02.17			

2) Bottom View















LED

Part Location

FM92A EAX61186802(3) 2010.01.08 RUBLEW

04EZ58044AA











0tES289t4V

JACK

Part Location

FM92A EAX61153301(10) 2009.12.31 LUBREW




02EZ58042AA

DMD


Part Location

← DMD FM92A EAX61420101 (3) 2009.12.03 N. C. M. →



06EZ58043AA





TEMP

Part Location

