



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 2, 2006

RE: LG Electronics, Inc.

FCC ID: BEJMG320D

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a photograph or diagram labeled to show the proper locate of both the GSM and BT antennas.
- 2) It is uncertain if the label is on the battery cover or battery compartment. Please note that the FCC does not allow it to be located on the cover itself.
- 3) This device appears to utilize a USB port and therefore considered as a PC peripheral device. It is uncertain if this will be Certified or DoC'd for the PC peripheral portion. Note that currently the device labeling and manual do not appear to be labeled for a DoC. Please explain/correct as necessary. If this is being Certified for a PC peripheral, please update the 731 form for equipment type JBP.
- 4) 731 form should be updated for DSS equipment type as well.
- 5) Please confirm that Bluetooth was investigated for all 3 axis and worse case data provided.
- 6) The device manual should include the appropriate Part 15.105, 15.21, and 15.19 information. Please update.
- 7) Kindly comment on where information regarding both DC voltages AND currents applied into the several elements of the final radio frequency amplifying device for normal operation over the power range been provided? (2.1033(c)(8)) can be found, or provide as necessary.
- 8) It does not appear that > 1% rule was followed for emissions near the fundamental for Part 22/24. Please review.
- 9) Please confirm that GPRS mode does not operate with voice mode active (i.e. at the head).
- 10) Please provide test configuration photographs for SAR that shows appropriate body spacings and accessories as tested.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.