Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

B.1 Conducted Emission Measurement



FRONT VIEW



BACK VIEW


File Number: C1M1810098 Report Number: EM-F180476, EM-F180477, EM-F180478, EM-F180479

New Taipei City244, Taiwan


Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz



Frequency Above to 1GHz



File Number: C1M1810098 Report Number: EM-F180476, EM-F180477, EM-F180478, EM-F180479



Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

B.3 RF Conducted Measurement

