

APPENDIX 3: Photographs of test setup

Conducted Emission



Front



Rear

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Radiated Spurious Emission



Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Pre-check for Worst Case Position

X-axis




Y-axis



Z-axis



Antenna Terminal Conducted Test



End of Report