



August 1, 2006

RE: FCC ID: BV8MBS900A100_ATCB003807

Attention: Rick McMurray; Kathy Grzovic

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that it appears that the label is located under the cover of the device. Please note that the FCC ID label is to be on the outside of the device. Please explain and please provide a label on the outside of the device.

Response: The label location in the exhibit is in fact readily viewable on the outside of the device. This is a 19 inch rack and the label is mounted on the outside surface of one of the sides. Mounted covers are flush with the surface shown, located in the recessed areas shown around the sides and top.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.