

March 17, 2000

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

REFERENCE: BV8MCS800A025 (EA96755 and EA96774)

To Whom It May Concern:

The above mentioned composite certifications were submitted on February 11 and 14, 2000. I would like to request that the following administrative changes be made to these submittals as follows:

BV8MCS800A025 (EA96755): Composite Submittal Part 15.247 / Part 90

1. On the 731 Form (item 10) please change the equipment code to TNB (not GVH as listed).
2. Please change the description on the Test Report and the FCC submittal to read: FCC Part 15.247 (not FCC Part 15.2439 as stated).

BV8MCS800A025 (EA96774): Composite Submittal Part 15.247 / Part 90

1. On the 731 Form (item 10), please change the equipment code to DSS (not DXX as listed).
2. Please change the description on the Test Report and in the FCC submittal to read: FCC Part 15.247 (not 15.2439 as stated.)

If you have any questions regarding these changes, please call me or email me.

Thank you for your prompt attention to this matter.

Sincerely,

Patty Terilli
Chomerics
Test Services Coordinator
77 Dragon Court
Woburn, MA 01888
781-939-4158
FAX: 781-935-2758