




FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 L/MKR 21.95 MHz
REF -45.0 dBm ATTEN 10 dB -68.22 dBm



FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 L/MKR 20.25 MHz
REF -45.0 dBm ATTEN 10 dB -68.32 dBm




~~hp~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 L/AMKR 21.95 MHz
REF -45.0 dBm ATTEN 10 dB -68.80 dBm




START 450 kHz STOP 30.00 MHz
#RES BW 10 kHz #VBW 300 kHz SWP 890 msec

~~hp~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 L/BMCR 21.95 MHz
REF -45.0 dBm ATTEN 10 dB -68.91 dBm




START 450 kHz STOP 30.00 MHz
#RES BW 10 kHz #VBW 300 kHz SWP 890 msec


~~/P~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 Transwitch
REF -60.0 dBm ATTEN 10 dB PG 25.0 dB



~~/P~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 Transwitch
REF -60.0 dBm ATTEN 10 dB PG 25.0 dB




hp FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 SPUR MKR 64.0 MHz
REF -35.0 dBm ATTEN 10 dB -46.02 dBm




START 30.0 MHz STOP 1.0000 GHz
#RES BW 100 kHz #VBW 300 kHz SWP 290 msec

hp FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 SPUR MKR 71.2 MHz
REF -35.0 dBm ATTEN 10 dB -46.24 dBm




START 30.0 MHz STOP 1.0000 GHz
#RES BW 100 kHz #VBW 300 kHz SWP 290 msec

~~h~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 (PIX) MKR 61.30 MHz
REF -30.0 dBm ATTEN 10 dB -40.95 dBm




START 56.25 MHz STOP 66.25 MHz
#RES BW 100 kHz #VBW 300 kHz #SWP 20 msec

~~h~~ FCC ID: C5F7NF0006 (DTMI-5NF01) CH.3 (AUD) MKR 65.80 MHz
REF -30.0 dBm ATTEN 10 dB -55.11 dBm




START 56.25 MHz STOP 66.25 MHz
#RES BW 100 kHz #VBW 300 kHz #SWP 20 msec

FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 (PIX) MKR 67.28 MHz
REF -30.0 dBm ATTEN 10 dB -41.22 dBm



START 62.25 MHz STOP 72.25 MHz
#RES BW 100 kHz #VBW 300 kHz #SWP 20 msec

FCC ID: C5F7NF0006 (DTMI-5NF01) CH.4 (AUD) MKR 71.78 MHz
REF -30.0 dBm ATTEN 10 dB -55.37 dBm



START 62.25 MHz STOP 72.25 MHz
#RES BW 100 kHz #VBW 300 kHz #SWP 20 msec