

Federal Communications Commission
7345 Oakland Mills Road
Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: C89ICERINGLITE (new FCC ID)

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by us (Dynamics Hong Kong Limite) will establish a new FCC ID under our own grantee code for the purpose of marketing.

The original grant applied to us (Dynamics Hong Kong Limited) with FCC ID: C89RINGLITE remains valid.

Per 2.933(b)

- 1.) The original identification is: FCC ID: C89RINGLITE
- 2.) The original granted date is: 12/18/2012
- 3.) The equipment is electrically identical, Only the FCC ID number, Brand Name are different (Change the brand:Ice Mobile to Ice Mobile, Ring).
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- External Photos
- ID Lable and Location Info

Sincerely yours,

A handwritten signature in blue ink is positioned to the left of a circular purple stamp. The stamp contains the text "DYNAMICS HONG KONG LIMITED" around the perimeter and Chinese characters in the center.

Dynamics Hong Kong Limited
Contact person: Thapa Rajendra Kumar
Title: Director
Tel: +852-23111980