



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

March 17th, 2004

Southwest Microwave, Inc.
9055 S. McKemy Street,
Tempe, AZ 85284-2946

Equipment: FCC ID: CA6MTP

Gentlemen,

Test performed on this date for Southwest Microwave, Inc. on model MTP at M. Flom Associates, Inc. indicates that the product satisfies the requirements of FCC Rule Part 15.209 over the frequency range 30MHz – 1GHz.

The attached data is for incorporation into a final report by Southwest Microwave, Inc. for submission to the FCC.

Thank you for your business and we look forward to serving you again.

Sincerely,

A handwritten signature in black ink, appearing to read 'D. Lee', is positioned above the typed name of the signatory.

David E. Lee
Laboratory Test Manager
M. Flom Associates, Inc.

DL/del