



1948142-0000 19C16536
762-870MHz 100003087

Caution
Do not remove or
switch load while
transmitting.
This may damage
the output stage.

10 6-16 8 VDC
15A Max

0 5 10 15cm

REPORT 2374
FCC ID: CASTBA8K2





0 5 10 15cm

REPORT 2374
FCC ID: CA5TBA8K2

ZAI




REPORT 2374
FCC ID: CASTBANK2



0
5
10
15cm

TANK 2374
ECC-CASTBANK2
USA CODE
REMOVED


CAUTION
DO NOT TOUCH THE PROBE TIPS
OR THE CONTACTS OF THE ZIF CONNECTOR
WHEN THE PROBE IS IN CONTACT WITH THE
DEVICE UNDER TEST.







0 5 10 15cm
REPORT 2574
FCC ID: CASTBAK2





REPORT 2374
 FCC ID: CASTBA8K2



0 5 10 15cm



REPORT 2374
FCC ID: CASTBA8K2



0
5
10
15cm



T801-20-0000
Rev 12
13122208
Tait Electronics Limited
Made in Spain, Zwickau



REPORT 2374
FCC ID: CASTB8K2



0 5 10 15cm

H50
Output
1.5 AMP
13.8VDC
13.8VDC
13.8VDC

102000433
ID: 797A-TB8K2
FCC ID: CASTBA8K2
Type Code
R50p2006
TB8K2
Made in New Zealand by Tait Electronics Ltd



REPORT 2374
FCC ID: CASTBA8K2



0
5
10
15cm