

Tait Limited

## Internal Photographs Exhibit

(February 2017)



Product:	TB9315-H1H0-0000-A100-10
Type code:	TBCC0E
FCC ID:	CASTBCC0E
IC:	737A-TBCC0E




Photograph 01: Reciter module – Internal (Receiver PCB side)

Tait Limited  
245 Woodridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)




Photograph 02: Reciter module – Internal (Control PCB side)

Tait Limited  
245 Woodridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)




Photograph 03: Reciter Receiver PCB – Top (with shields)

Tait Limited  
245 Woodbridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)




Photograph 04: Reciter Receiver PCB – Top (without shields)

Tait Limited  
245 Woolbridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)




Photograph 05: Reciter Receiver PCB – Bottom




Photograph 06: Reciter Control PCB – Top (with shields)

Tait Limited  
245 Woolbridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)




Photograph 07: Reciter Control PCB – Top (without shields)


Tait Limited  
245 Woolbridge Road, Christchurch 8051  
PO Box 1645 CHCH  
New Zealand  
+64 3 358 3399, [www.taitradio.com](http://www.taitradio.com)



Photograph 08: Reciter Control PCB – Bottom



Photograph 09: Reciter TXF PCB - Top



Photograph 10: Reciter TXF PCB – Top (without shields)



Photograph 11: Reciter TXF PCB - Bottom