


From: "oetech@fccsun27w.fcc.gov" <oetech@fccsun27w.fcc.gov>
To: hotline <hotline@acbcert.com>
Subject: Response to Inquiry to FCC (Tracking Number 605285) (TCB)

**Inquiry:**

---Reply from Customer on 10/20/2011---

Client is asking if there is a status on this. Please advise.
Thank You,
Tim Johnson
ACB

Response:

The change of the antenna with the capacitor being considered as part of the antenna would be a Class II permissive change.

[Test Data](#)

Do not reply to this message. Please select the [Reply to an Inquiry Response](#) link from the OET Inquiry System to add any additional information pertaining to this inquiry.