

Toshiba Corporation, FCC ID: CJ6UPA3547G3, Assessment NO.: AN07T6587, Notice#1 [Inbox](#)

☆ from "tim.dwyer@ccsemc.com" <tim.dwyer@ccsemc.com> [hide details](#) Mar 12 (to Thu.Chan@ccsemc.com
cc tim.dwyer@ccsemc.com,
september.radecki@ccsemc.com
date Mar 12, 2007 10:21 PM
subject Toshiba Corporation, FCC ID: CJ6UPA3547G3, Assessment NO.: AN07T6587

Dear Thu,

The application review is complete. There are a few issues related to documentation. I have questions.

AN07T6587 TOSHIBA CJ6UPA3547G3 C2PC

1. The host user manual does not include specific operating instructions and warning exposure. As submitted, the statement in the manual addresses only a Bluetooth device. Please provide evaluation information related to the modular device to include maximum SAR and SAR warning statements for portable operation.

2. The Bluetooth device referred to in the host manual is not considered in either the host or the device. Please provide evaluation information related to the Bluetooth device with regard to power and SAR issues.

3. The grant condition on the original grant specifies that the end user shall have no right to remove or install the device. The document "3G-manual.pdf" provides instructions for removal and installation. Please explain the intended purpose of the document.

4. Internal photos document should show the modular device mounted. Please extract a copy of the SAR report photos document to the internal photos document.

5. External photos document should show exterior of host. Please extract a copy of the SAR report photos document to the external photos document.

Best regards,

Tim Dwyer

The items indicated above must be submitted before processing can continue on the application. Failure to provide the requested information within 30 days of the original application dismissal and forfeiture of the filing fee. Also, please note that partial responses are not acceptable and should not be submitted. Any questions about the content of this message should be directed to the e-mail address listed below the name of the sender.

[Reply](#) [Reply to all](#) [Forward](#) [Invite tim.dwyer@ccsemc.com to Gmail](#)

☆ from **September Radecki** <september.radecki@ccsemc.com> [hide details](#) 4:51 pm Mar 14, 2007 to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>

cc Thu Chan <thu.chan@ccsemc.com>,
Christine Vu <christine.vu@ccsemc.com>,
Chi Tsou <chi.tsou@ccsemc.com>,
Mike Kuo <mike.kuo@ccsemc.com>

date Mar 14, 2007 4:51 PM

subject RE: Toshiba Corporation, FCC ID: CJ6UPA3547G3, Assessment NO.: AN07T6587

Hi Tim,

Here are the answers to the questions on the above referenced application:

1. The host user manual does not include specific operating instructions and warning exposure. As submitted, the statement in the manual addresses only a Bluetooth device exposure/SAR information related to the modular device to include maximum SAR and SAR warning statements for portable operation.

CCS Reply: In this application, only the 3G Radio Module is installed in the tablet host. Bluetooth radio modules are not applicable to this application. Attached please find the signed by the applicant. In accordance with FCC policy, measured SAR values are not in the user manual.

2. The Bluetooth device referred to in the host manual is not considered in either the internal or external photos. Please provide evaluation information related to the Bluetooth device with regard to power and SAR issues.

CCS Reply: Please refer to the reply to question #1, Bluetooth module is not installed.

3. The grant condition on the original grant specifies that the end user shall have no right to remove or install the device. The document "3G-manual.pdf" provides instructions for the removal and installation of the device. Please explain the intended purpose of the document.

CCS Reply: The 3G-manual submitted only contains software installation procedures. There is no hardware installation procedures provided in the document. In accordance with FCC policy, hardware information, 3G radio module will always be installed by the applicant or its authorized agent. Installation of 3G module is not allowed.

4. Internal photos document should show the modular device mounted. Please extract a copy from the SAR report photos document to the internal photos document.

CCS Reply: Please see attached revised exhibit.

5. External photos document should show exterior of host. Please extract a copy from the SAR report photos document to the external photos document.

CCS Reply: Please see attached revised exhibit.

Thank you for your patience.

Kindest regards,

September

- Show quoted text -

3 attachments — [Download all attachments](#)

 **External Photos.pdf**
210K [View as HTML](#) [Download](#)

 **Internal Photos.pdf**
189K [View as HTML](#) [Download](#)

 **Toshiba Marketing Statement_R400 Manual.pdf**
60K [View as HTML](#) [Download](#)