

answer: Toshiba Corporation, FCC ID: CJ6UPA3655WL, Assessment NO.: AN08T8315 & AN08T8316 Notice#1

1 message

Claire Hoque <claire.hoque@ccsemc.com>

Thu, Aug 28, 2008 at 5:37 PM

To: "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>, Tim Dwyer - TCB <Timothy_Dwyer@ieee.org>, "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>
Cc: Thu Chan <thu.chan@ccsemc.com>, Tina Chu <tina.chu@ccsemc.com>, Christine Vu <christine.vu@ccsemc.com>

Hi Tim,

Here are the answers.

Q1. RF Exposure warning in the manual mentions Bluetooth device specifically, but does not mention WLAN module. Please provide revised manual or separate document showing RF exposure warning to be placed in manual.

<answer> Please see the attached file containing the WLAN FCC info. Let me know if any additional info is required.

Q2. Bluetooth is mentioned in the manual, and co-location is mentioned in the test report, but there is no BT application or evaluation information. Please confirm that no evaluation for BT co-location or other issues is required in this application and that applicant is aware of responsibilities related to use of the Bluetooth module in the host product.

<answer> The tablet is collocated with BT module as I indicated at the outset of the project and the FCC ID for the module was provided. The BT module is the identical to the one investigated with the Wengen 10 model granted previously

Q3: The WLAN module used in this application has capability for 1x2 MIMO operation. Please confirm that only a single transmit antenna is used in this application.

<answer> This is to conform that only a single transmit antenna is used with these notebook PC with this SP 1x2 module model.

Thanks,

Claire Hoque
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538, USA
Tel: (510) 771-1123
Fax: (510) 661-0888

-----Original Message-----

From: Timothy M. Dwyer
Sent: Thursday, August 28, 2008 12:46 PM
To: Thu Chan
Cc: Claire Hoque; Timothy M. Dwyer
Subject: Toshiba Corporation, FCC ID: CJ6UPA3655WL, Assessment NO.: AN08T8315 & AN08T8316 Notice#1

Hello Thu, Claire,

Review of the applications is complete. Please reply asap to the following issues so that the application deadline can be met.

Q1. RF Exposure warning in the manual mentions Bluetooth device specifically, but does not mention WLAN module. Please provide revised manual or separate document showing RF exposure warning to be placed in manual.

Q2. Bluetooth is mentioned in the manual, and co-location is mentioned in the test report, but there is no BT application or evaluation information. Please confirm that no evaluation for BT co-location or other issues is required in this application and that applicant is aware of responsibilities related to use of the Bluetooth module in the host product.

Q3: The WLAN module used in this application has capability for 1x2 MIMO operation. Please confirm that only a single transmit antenna is used in this application.

The items indicated above st be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer
Technical Reviewer

 **FCC WLAN Manual info.pdf**
185K
